




World Famous Upholstery

- We offer the finest in upholstery
- Partial and Complete Mail Order Kits
- Installation Available ——with Free Tech Support



Complete Selection of Mail Order Parts

- Sheet Metal- many parts available in stainless, Mechanical, Electrical, Suspension, Steering, Brakes, Exhaust, Engines, Service ——Installation Available

Restoration Service



Stainless Steel Fuel Tanks

PO Box 245 Wyoming, RI 02898 401-539-3010 401-539-7861 (fax)
www.bassetjag.com jagwillie@ids.net
Monday thru Friday
8:30am—5:00pm

JAGUAR SEDAN CATALOG
SALES, TERMS AND CONDITIONS

PAYMENT:

CREDIT CARDS: Please list all numbers on credit card, expiration date, 3-digit CVV code on back of card and the name of the card holder.

C.O.D.: An additional \$8.50 C.O.D. fee is charged in addition to shipping and handling fees.

SHIPPING:

All shipments are made my United Parcel Service. UPS is available to the 48 continental states, Hawaii, Alaska, Puerto Rico and the provinces of Ontario, Quebec and British Columbia. Federal Express or Emery Air Freight shipments are available upon request only. Please note that shipments to Hawaii are sent UPS Blue Label Air Only.

Canadian shipments which can't be shipped by UPS are made via United States Postal Service and are subject to additional shipping charges.

If a C.O.D. order is refused and the package is returned to us by UPS, the customer will be liable for all the shipping charges incurred before reshipment.

Any items damaged or lost in shipment are the responsibility of the carrier. Inspect all orders upon receipt. In the event of damage, retain the shipping carton and packing material. Promptly notify the carrier and request a damage inspection. The carrier will evaluate the claim and contact us if necessary.

ORDERS, BACKORDERS AND RETURNS:

Orders are taken over the phone, by mail, e-mail, fax or in person. If you are planning to pick up your order, please call us in advance to place the order and to let us know what time you are expecting to arrive. All upholstery and sheet metal orders are custom made to order and take approximately 3 weeks for preparation and require a 50% deposit at the time of the initial order. If you are planning to mail your order, please be sure to give us complete car information: model, make and year.

On all back orders, items which are temporarily out of stock, you will receive notice on the invoice enclosed in your order. Please advise if you wish to cancel the item(s) indicated. Any items that are not cancelled will be shipped when available. There is a 20% restocking charge on any items not cancelled prior to the shipping date.

We must be notified within seven (7) days upon receipt of your order if there are any errors or defective merchandise for return credit. Returns must be authorized and must be shipped prepaid to our street address. Returns due to customer error are subject to a 20% restocking charge and all shipping charges. **There are no returns on electrical, upholstery and/or custom made items unless they are proven defective or the incorrect merchandise is delivered.**

All parts are guaranteed for workmanship and materials. Guarantee does not cover faulty installation by the customer.

TECHNICAL ADVICE:

Free technical advice will gladly be given for any problem or project. We ask, however, that you do not use the toll free order line for technical calls, please call us at (401) 539-3010 only.

PRICES ARE SUBJECT TO CHANGE WITHOUT NOTICE

TABLE OF CONTENTS

<p>INTERIORS</p> <p>REBUILT SEATS.....7</p> <p>SEAT COVERS.....7</p> <p>HEADREST COVERS.....7</p> <p>CENTER CONSOLE COVER.....7</p> <p>PACKAGE SHELF.....7</p> <p>RUG SETS.....8</p> <p>THROW RUGS.....8</p> <p>UNDERFELTS.....8</p> <p>VINYL KITS.....9</p> <p>TRUNK PANELS.....9</p> <p>DOOR PANELS.....9</p> <p>ARMRESTS.....9</p> <p>HEADLINERS.....9</p> <p>WINDLACING.....10</p> <p>CONVERTIBLE TOPS.....10</p> <p>UPHOLSTERY SUPPLIES.....10</p> <p>UPHOLSTERY YARD GOODS.....10</p> <p>LEXOL LEATHER PRODUCTS.....10</p> <p>WOOD PRODUCTS.....11</p> <p>RUBBER PARTS.....11</p> <p>MOLDED RUBBER PARTS.....11</p> <p>BODY.....11</p> <p>BUMPER.....11</p> <p>ELECTRICAL.....11</p> <p>ENGINE.....11</p> <p>HOLE PLUGS.....12</p> <p>LENS GASKETS.....12</p> <p>LIGHT PADS.....12</p> <p>MOUNTS.....12</p> <p>PEDAL PADS.....13</p> <p>WINDSHIELD & WIPERS.....13</p> <p>MISCELLANEOUS.....13</p> <p>WEATHERSTRIPPING.....13</p> <p>DOORS AND SILLS.....13</p> <p>HOOD.....14</p> <p>SUNROOF.....14</p> <p>TRUNK.....14</p>	<p>WINDOWS.....14</p> <p>MISCELLANEOUS.....14</p> <p>GROMMETS.....14</p> <p>INDIVIDUAL GROMMETS.....14-16</p> <p>RUBBER GROMMET KITS.....16</p> <p>WINDOWS.....17</p> <p>WINDSHIELDS.....17</p> <p>WINDSHIELD SEALS.....17</p> <p>BACKLIGHT SEALS.....17</p> <p>WINDOW SCRAPERS.....17</p> <p>WINDOW CHANNEL FELT.....17</p> <p>WIPER BLADES.....17</p> <p>DEFROSTER HOSE.....17</p> <p>ELECTRICAL.....17</p> <p>BULLET CONNECTORS.....17</p> <p>IGNITION PARTS.....17</p> <p>DISTRIBUTORS.....18</p> <p>DISTRIBUTOR COMPONENTS.....18</p> <p>FUSES AND FUSE BOXES.....18</p> <p>GENERATOR COMPONENTS.....19</p> <p>MISCELLANEOUS ELECTRICAL ITEMS.....19</p> <p>RELAYS.....19</p> <p>INDIVIDUAL “JEWELS” AND BEZELS.....19</p> <p>“JEWEL” AND BEZEL SETS.....19</p> <p>SWITCH KNOBS.....19</p> <p>SWITCHES.....20</p> <p>LIGHTS AND LENSES.....20</p> <p>HEADLIGHTS AND FOGLIGHTS.....21</p> <p>BULBS.....21</p> <p>REBUILT GAUGES.....21</p> <p>BRAKE PARTS.....21</p> <p>BRAKE PADS.....21</p> <p>HANDBRAKE PADS.....22</p> <p>BRAKE SHOES.....22</p> <p>BRAKE ROTORS.....22</p> <p>BRAKE MASTER CYLINDERS.....22</p> <p>BRAKE CALIPER ASSEMBLIES.....22</p> <p>BRAKE CALIPER PISTONS.....22</p>
--	---

TABLE OF CONTENTS

CLUTCH MASTER CYLINDERS.....22	BANJO FILTERS.....28
CLUTCH SLAVE CYLINDERS.....22	CARB REBUILDING KITS.....28
POWER BRAKE SERVO UNIT.....22	FUEL PUMPS.....28
BRAKE REBUILD KITS.....22	FUEL FILTERS.....29
CLUTCH REBUILD KITS.....23	FUEL TANK SENDING UNITS.....29
SERVO REBUILD KITS.....23	CARB ADJUSTING TOOLS.....29
BRAKE HOSES.....23	MISCELLANEOUS.....29
BRAKE PIPES.....23	OIL SYSTEM.....29
CLUTCH HOSE.....23	OIL FILTERS.....29
MISCELLANEOUS BRAKE PARTS.....23	OIL FILTER CONVERSION KIT.....29
SILICONE BRAKE FLUID.....24	OIL PUMPS.....29
ENGINE PARTS.....24	MISCELLANEOUS.....29
PISTON SETS.....24	COOLING SYSTEM.....30
PISTON RINGS.....24	WATER PUMPS.....30
BEARINGS.....24	BEARINGS AND SEALS.....30
GASKET SETS.....25	FAN CLUTCHES.....30
CAM COVER GASKET SETS.....25	FAN BELTS.....30
INDIVIDUAL GASKETS.....25	MISCELLANEOUS.....30
ENGINE.....25	AIR CONDITIONING.....31
“O” RINGS.....25	EXHAUST SYSTEMS.....31
ENGINE SEALING WASHERS.....25	CABLES.....31
VALVES, GUIDES AND SPRINGS.....25	TACHOMETER CABLES.....31
VALVE ADJUSTING SHIMS.....26	CABLE DRIVE GEARBOXES.....31
TIMING COMPONENTS.....26	SUSPENSION.....31
TAPPET HOLDOWN KITS.....26	BALL JOINTS.....31
CAMSHAFT TIMING TOOLS.....26	TIE RODS AND ENDS.....32
HARMONIC BALANCER.....27	SUSPENSION BUSHINGS.....32
MISCELLANEOUS ENGINE PARTS.....27	REAR SUSPENSION MOUNTS.....32
CLUTCH PARTS.....27	SUSPENSION SPRINGS.....32
MISCELLANEOUS.....27	UNIVERSAL JOINTS.....32
RING GEARS.....27	SHOCK ABSORBERTS.....33
TRANSMISSION PARTS.....27	REBUILT STEERING RACKS.....33
AUTOMATIC TRANSMISSION FILTER KITS.....27	RACK AND PINION PARTS.....33
STD TRANSMISSION GASKETS.....27	REBOUND RUBBERS.....33
OVERDRIVE GASKETS.....28	FRONT WHEEL BEARINGS.....33
MISCELLANEOUS.....28	REAR WHEEL BEARINGS.....33
FUEL SYSTEM.....28	DIFFERENTIAL BEARINGS.....33
AIR FILTERS.....28	WHEEL BEARING AND SEAL KITS.....34

TABLE OF CONTENTS

OIL SEALS34	MAINTENANCE CHARTS.....39
DIFFERENTIAL SEALS.....34	OWNER'S HANDBOOKS.....39
ENGINE SEALS.....34	
TRANSMISSION SEALS STD TRANSMISSION.....34	POSTERS.....40
AUTOMATIC TRANS.....34	
WHEEL SEALS.....34	
AXLE SEALS.....34	
MISCELLANEOUS SEALS.....34	
POWER STEERING PUMP SEAL KIT.....35	
TIRES AND WHEELS35	
HARDWARE35	
ENGINE COMPARTMENT HARDWARE.....35	
EXTERIOR HARDWARE.....35	
INTERIOR HARDWARE.....36	
TRIM ATTACHMENT RIVETS.....36	
SNAPS-ALL TYPES.....36	
INTERIOR TRIM SCREWS.....36	
WIRING HARNESS CLIPS.....36	
MISCELLANEOUS HARDWARE.....36	
PAINT37	
EMBLEMS AND DECALS37	
DATA PLATES.....37	
EMBLEMS.....38	
BODY FITTINGS & CHROME38	
EXTERIOR.....38	
HUBCAPS.....38	
INTERIOR PIECES.....38	
LIGHT HOUSINGS.....38	
NUTS AND WASHERS.....38	
ACCESSORIES38	
SPOKE BRUSHES.....38	
CAR COVERS.....38	
JAGUAR QUARTERLIES.....38	
LITERATURE.....39	
SPARE PARTS CATALOGUES.....39	
ASSORTED LITERATURE.....39	
SERVICE MANUALS.....39	

INTERIORS

All of our upholstery is custom fabricated in-house by own Master Upholsterers. John and Frank have over 70 years of combined experience with automotive upholstery and work with precise patterns we have developed over the past 20 years.

We use the finest materials and supplies available, period. Our materials, colors and finishing touches are authentic and the detail and fit are perfect.

Our rug corners are mitered, our convertible tops are topstitched and our replacement seats are exactly as original with the proper number of pleats on different models. The individual pleats are handcut and matched so that when the seat is sewn and assembled, the grain of the leather on all of the pleats matches. Our trunk panels, vinyl kits and door panels are superior to the original. In order to eliminate warp and delamination, which is common in the original panels, we do not use cardboard or thin plywood.

All of our upholstery products are crafted with perfection in mind and are of show quality, regardless of whether or not they will be installed in a show car.

If you intend to replace all of the leather pieces in the interior, it is advised that you have all of them done at the same time, thus ensuring a correct dye and color match.

The choices of material colors are as follows:

Old Biscuit is now available with the proper antique finish.

Leather: Red, Black, Blue, Grey, Tan, Suede Green, Russet, Old Biscuit and New Biscuit.

Wool Carpet, High Pile: Red, Black, Dark Blue, Grey, Tan, Green, Russet, Old Biscuit and New Biscuit.

Hardura: Red, Black, Dark Blue, Grey, Tan, Green, Russet, Old Biscuit and New Biscuit.

British Vinyl: Red, Black, Blue, Grey, Suede Green, Russet, Old Biscuit and New Biscuit.

Moquette: Red, Black, Blue, Grey, Tan, Suede Green, Russet, Old Biscuit and New Biscuit.

Canvas (Stayfast): Black on Black and Tan on Tan.

****note:** Black on Tan, Tan on Black and Dark Blue on Tan are special ordered and are not stocked.

German Cloth: Black on Tan, Tan on Tan, Dark Blue on Tan, Dark Brown on Tan, Grey on Grey and White on Tan.

Wood Broadcloth Headliner: Grey, Camel and Green.

REBUILT SEATS

Our seats are furnished with leather piping and leather side panel trim pieces. This is done to ensure no color difference between materials due to again in years to come.

We offer a complete rebuilding of your seats. We must be furnished with the originals: Crate properly and ship (we suggest UPS).

Rebuilt seats have the seat frames sandblasted and painted, new foam pieces and cushions installed and new leather seat covers with moquette backs fitted.

MARK 7			MARK 8		
SX10	Rebuilt Front Bucket Seats	\$2600.00	SX13	Rebuilt Front Bucket Seats	\$2600.00
SX11	Rebuilt Front Bench Seat	\$2600.00	SX14	Rebuilt Front Bench Seats	\$2600.00
SX12	Rebuilt Rear Seats	\$2600.00	SX15	Rebuilt Rear Seats	\$2600.00
MARK 9			MARK 2		
SX16	Rebuilt Front Bucket Seats	\$2600.00	SX30	Rebuilt Front Bucket Seats	\$2600.00
SX17	Rebuilt Front Bench Seats	\$2600.00	SX31	Rebuilt Rear Seats	\$2600.00
SX18	Rebuilt Rear Seats	\$2600.00	XJ6, XJ12		
XJS			SX40	Rebuilt Front Bucket Seats	\$2600.00
SX42	Rebuilt Front Bucket Seats	\$1900.00	SX41	Rebuilt Rear Bench Seat	\$1800.00
SX43	Rebuilt Rear Bench Seat	\$1800.00			

SEAT COVERS

Our leather seat covers are made to order and are not stocked. They have the proper construction and the correct number of pleats as the originals. There is no universal cover that fits any given model. It is your responsibility to give us the correct year, model and type of seats so we can provide the correct cover. Seat covers are not returnable.

MARK 7			MARK 8		
SC8	Front Bucket Seat Covers	\$1000.00	SC10	Front Bucket Seat Covers	\$1000.00
SC9	Seat Covers, Rear Bench Seat	\$1200.00	SC11	Seat Covers, Front Bench Seat	\$1300.00
MARK 9			SC12	Seat Covers, Rear Bench Seat	\$1200.00
SC16	Front Bucket Seat Covers	\$1000.00	MARK 2		
SC17	Seat Covers, Front Bench Seat	\$1300.00	SC20	Front Bucket Seat Covers	\$1000.00
SC18	Seat Covers, Rear Bench Seat	\$1200.00	SC21	Seat Covers, Rear Bench Seat	\$1200.00
XJ6, XJ12			XJS		
SC30	Front Bucket Seat Covers	\$1200.00	SC32	Front Bucket Seat Covers	\$1200.00
SC31	Seat Covers, Rear Bench Seats	\$1100.0	SC33	Seat Covers, Rear Bench Seat	\$1100.00
HEADREST COVERS			CENTER COSOLE COVER		
HC5	Headrest Covers, XJ6, XJ12	\$ 200.00	CC10	Center Console Recovering, MK 2	\$ 225.00
HC6	Headrest Covers, XJS	\$ 200.00	PACKAGE SHELF		
			PSR	Package Shelf Recovering, MK 2 Recovered with carpet and leather	\$ 94.50

RUG SETS

Our rug sets are made of high pile wool and come with all necessary hardware. In order for these rugs to fit properly, our **underfelts are required**. Please call for quotes on any other cars not listed.

MARK 7

RK60	Hile Pile Rug Set—Fits left hand drive, standard trans	\$575.00
RK62	Hile Pile Rug Set—Fits right hand drive, standard trans	\$575.00

MARK 9

RK72	Hile Pile Rug Set—Fits left hand drive, standard trans	\$575.00
RK70	Hile Pile Rug Set—Fits left hand drive, automatic trans	\$575.00

3.4S, 3.8S

RK78	High Pile Rug Set—Fits left hand drive, standard trans	\$575.00
------	--	----------

420

RK80	High Pile Rug Set—Fits left hand drive, standard trans	\$575.00
------	--	----------

XK6, XJ12—Series II, 1974-78

RK84	High Pile Rug Set, Fits left hand drive, automatic trans	\$575.00
------	--	----------

XJS

RK95	High Pile Rug Set— Fits left hand drive, automatic trans-comes with moquette trim pieces for door panels	\$575.00
------	--	----------

MARK 8

RK64	High Pile Rug Set—Fits left hand drive, standard trans	\$575.00
RK66	High Pile Rug Set—Fits right hand drive, standard trans	\$575.00
RK68	High Pile Rug Set—Fits left hand drive, automatic trans	\$575.00

MARK 2

RK76	High Pile Rug Set—Fits left hand drive, standard trans	\$575.00
RK74	High Pile Rug Set—Fits left hand drive, automatic trans	\$575.00

340

RK88	High Pile Rug Set—Fits left hand drive, standard trans	\$575.00
------	--	----------

XK6, XJ12—Series I, 1969-73

RK82	High Pile Rug Set—Fits left hand drive, automatic trans	\$575.00
------	---	----------

XK6, XJ12—Series III, 1978-85

RK89	High Pile Rug Set, Fits left hand drive, automatic trans	\$575.00
------	--	----------

THROW RUGS

Throw rugs are available for any rug kit. These rugs are designed to cover the main floor rugs and prevent them from becoming soiled. They are available in the same colors as the rug sets.

RK85	Throw Rugs	\$106.50
------	------------	----------

UNDERFELTS

Underfelts are the jute pads that go between the rugs, the metal floors and the firewall of your car. They are necessary for the rugs to fit properly.

UF4	Underfelts—Mk 7, Mk 8 & Mk 9	\$ 60.00	UF10	Underfelt Yard Goods—Mk 2	\$ 40.00
-----	------------------------------	----------	------	---------------------------	----------

At this time, we can only offer this set of underfelts in bulk (uncut). We expect to be able to offer pre-cut sets at some point in the future.

VINYL KITS

All vinyl kit pieces come with the proper padding cut for the area to be covered and are made with British Vinyl.

VK20	Vinyl Kit, Mk 7	\$300.00	VK21	Vinyl Kit, Mk 8	\$300.00
VK22	Vinyl Kit, Mk 9	\$300.00			

Vinyl kits contain: (1) large underdash panel, (2) front kick panels, (2) door post panels (2) rear seat panels

VK29	Vinyl Kit, Mk 2	\$120.00			
------	-----------------	----------	--	--	--

Vinyl Kit contains: (2) front kick panels, (2) door post panels (2) small rear panels in rear seat area

TRUNK PANELS

Trunk panels are the panels which attach to the trunk lid. The trunk side panels attach to the sides of the trunk compartment and panel behind the rear seat.

TP20	Trunk Panel Set, Mk 7	\$350.00	TP21	Trunk Panel Set, Mk 8	\$350.00
TP22	Trunk Panel Set, Mk 9	\$350.00	TP20S	Trunk Side Panel Set, Mk 7	\$295.00
TP21S	Trunk Side Panel Set, Mk 8	\$295.00	TP22S	Trunk Side Panel, Mk 9	\$295.00
TM1	Hardura Trunk Mats and Spare Tire Cvr Mk 7, Mk 8, Mk9	\$300.00	TP30	Trunk Panel Set, Mk 1	\$140.00
TP35	Trunk Panel Set (grey), Mk 2—set contains the pair of side panels	\$220.00	TM2	Hardura Trunk Mat (grey), Mk 2	\$190.00

DOOR PANELS

All door panels are covered in British Vinyl. Piping and flap/fasteners are affixed where called for. Door panels do not include armrest and chrome. See **hardware section** for trim screw kit and door panel clips.

DP21	Door Panel Set for four doors, Mk 7- includes tool box doors & pocket pieces	\$660.00	DP22	Door Panel Set for four doors, Mk 8- includes tool box doors & pocket pieces	\$660.00
DP23	Door Panel Set for four doors, Mk 9- includes tool box doors & pocket pieces	\$660.00	DP30	Door Panel Set, Mk 2 Covered in British Vinyl	\$800.00
DP31	Door Panel Set, Mk 2 Covered in leather	\$995.00			

ARMRESTS

A3	Armrest Rebuild, Mk 7, Mk 8, Mk 9 You must send in your old bases	\$100.00	A5	Armrest Rebuild (set of 4), Mk 2—due to the complicated nature of this, armrests will only be rebuilt when accompanied by an order for door panels. Add \$75 for leather recovering instead of British Vinyl	\$375.00
----	---	----------	----	--	----------

HEADLINERS

Our headliners are handmade of heavyweight 100% wool broadcloth from patterns matched to the vehicle. This guarantees you a perfect kit. Where applicable, we also use a special foam backing which won't disintegrate from the heat as the original foam does.

MARK 4

HL20	D.H.C Headliner	\$402.50
HL21	Saloon Headliner with Sunroof	\$402.50

MARK 7

HL7	Headliner with sunroof	\$402.50
-----	------------------------	----------

MARK 9

HL9	Headliner with sunroof	\$475.00
-----	------------------------	----------

MARK 5

HL22	D.H.C Headliner	\$402.50
HL23	Saloon Headliner with Sunroof	\$402.50

MARK 8

HL8	Headliner with sunroof	\$402.50
-----	------------------------	----------

MARK 2

HL10	Headliner without sunroof Fits cars without sunvisor pockets	\$358.50	HL10A	Headliner without sunroof Fits cars with sunvisor pockets	\$358.50
------	---	----------	-------	--	----------

XJ6, XJ12

HL30	Headliner, 2 door coupes	CALL	HL31	Headliner, 4 door sedans	\$360.00
------	--------------------------	------	------	--------------------------	----------

XJS

HL35	Headliner	CALL
------	-----------	------

WINDLACING

Windlacing is the fuzzy moquette covered rubber used around doors and windshields. It acts as a wind seal to prevent drafts. Kits supply enough windlacing for the entire car. Mk 7, 8 and 9 also require the windlacing rubber set, R92C, which is the door rubber which lays next to the windlacing.

WL11	Mk 2, 3.4S, 3.8S Windlacing	\$ 98.50	WL12	Mk 7 Windlacing Kit	\$250.00
WL13	Mk 8 Windlacing Kit	\$250.00	WL14	Mk 9 Windlacing Kit	\$250.00
WL17	420 Windlacing	\$ 98.50	WL20	XJ6L & XJ12L Windlacing Available in black or New Bisquit	\$215.00

CONVERTIBLE TOPS

We make convertible tops that are precise reproductions of the original. They are made with piping borders and sewn with top stitching, exactly as original.

OT30	Convertible Top, Mk 4 DHC	\$550.00	OT31	Convertible Top, Mk 5 DHC	\$550.00
------	---------------------------	----------	------	---------------------------	----------

UPHOLSTERY SUPPLIES

UG	Upholstery Cement (quart)	\$ 15.00	UG1	Upholstery Cement (pint)	\$ 9.00
UB1	1" Upholstery Brush	\$ 1.00	UB2	Small Upholstery Brush	\$.55

UPHOLSTERY YARD GOODS—The available colors are listed at the beginning of the upholstery section

UM1	Conolly Leather (per square foot) Sold only by the hide (@45"/hide)	\$ 8.75	UM2	Wood Headliner Broadcloth (56" wide)	CALL
UM3H	High Pile Wood Carpet (40" wide)	CALL	UM5	British Vinyl (54" wide)	\$ 55.00
UM6	Wool Moquette (velour) (48" wide) Used for backs of seats, windlacing, rear areas, etc.	\$ 68.00			

LEXOL LEATHER PRODUCTS

We highly recommend these Lexol products. We use them in our shop and have found them to be very effective for the care of the leather in the cars.

Lexol-ph Balanced Leather Cleaner

Lexol Leather Conditioning & Preservative

LC1	1/2 Liter (16.9 oz) Lexol	*****	LCP1	1/2 Liter (16.9 oz) Lexol	*****
LC2	1 Liter (33.8 oz) Lexol	*****	LCP2	1 Liter (33.8 oz) Lexol	*****

Lexol Non-Greasy Neatsfoot

LN1	1/2 Liter (16.9 oz) Lexol	*****	LN2	1 Liter (33.8 oz) Lexol	*****
-----	---------------------------	-------	-----	-------------------------	-------

Wood Products

WBS1	Wood Bow Set, Mk 4 DHC—Sold as a complete set only. Contains front, middle and rear top bows and the rear tacking strips, all handmade with mahogany.	\$1100
------	---	--------

RUBBER PARTS

MOLDED RUBBER PARTS

BODY

RK	Gas Door Gasket (each) Mk 5 Mk 7, Mk 8, Mk 9	\$ 4.45	RL	Gas Cap Gasket, Mk 5	\$ 2.80
R7A	Steering Column Boot, Mk 5	\$ 65.80	R24	Gas Door Bumper, Mk 2 Hood Bumper, Mk 5 (each) (6 required)	\$.85
R24B	Hood Bumper (each) (6 required) Mk 7, Mk 8, Mk 9	\$.90	R25	Fender Mirror Pad (each) (2 required) Mk 7, Mk 8, Mk 9, Mk 2	\$ 1.65
R33	Clutch & Brake Dust Excluder (each) Mk 5 (2 required)	\$ 7.45	R47	Heater to Firewall Seal, Mk 8, Mk 9	\$ 7.25
R121	Dome Shaped Gas Cap Seal (each) (2 required) Mk 9	\$ 6.25	R162	Cowl Vent Seal, Mk 2, 380S, 420	\$ 20.40
R240	Fuel Filler Door Seal, XJS	\$ 14.50	R7	Steering Column Grommet, Mk 5	\$ 5.00

BUMPER

R49A	Bumperette to Bumper Rubber (each) (8 req) Mk 7, Mk 8, Mk 9, Mk 10, Mk 1, Mk 2, 420, 420G, XJ6, XJ12	\$ 1.40	R93	Rear Bumper Rubber MK 7, Mk 8, Mk 9	\$ 19.38
R94	Rear Bumper Rubber, Mk 2	\$ 19.38			

ELECTRICAL

R10	Dimmer Switch Cap Mk 5, Mk 7, Mk 8, Mk 9	\$ 9.85	R11	Solenoid Cable Boot (each) Mk 5, Mk 7, Mk 8, Mk 9, Mk 10, Mk 2	\$ 4.95
R12	Solenoid Button Boot (each) Mk 5, Mk 7, Mk 8, Mk 9, Mk 10, Mk 2	\$ 7.45	R131	Black Electrical Strapping (14' with 50 white buttons) Used on most sedans from early 60's to mid 70's	\$ 18.30
R134A	Horn Insulating Grommet (each) (2 req) Mk 8, Mk 9	\$ 4.15			

ENGINE

R30	Air Intake to Air Filter Sleeve. This is the round connector sleeve Mk 5, Mk 7, Mk 8, Mk 9	\$ 16.60	R30A	Air Intake to Air Filter Sleeve. This is the round connector sleeve. Fits Mk 2 with oil bath air cleaners. Fits all 3.4S, 3.8S, 420, Mk 10	\$ 11.40
R30B	Air Intake to Air Filter Sleeve. This is the oval connector sleeve. Fits Mk 9 with optional paper filter. Fits Mk 2 with paper filter.	\$ 15.30			

HOLE PLUGS

R27	Twisted Hole plug (each) For headlight bucket harness (2 req) Mk 5, Mk 7, Mk 8, Mk 9, Mk 10, Mk 1, Mk 2, 420, 420G, XJ6, XJ 12	\$ 6.25	R28	Firewall Hole Plug—For temp and oil gauge pressure line Mk 5, Mk 7, Mk 8, Mk 9, Mk 1	\$ 6.25
R151	5/8" Hole Plug (each) Used on the firewall (as required)	\$ 4.45	R152	1" Hole Plug (each) Used in various locations (as required)	\$ 5.65
R153	3" Hole Plug Used for transmission inspection hole	\$ 9.85			

LENS GASKETS

RM	Taillight Lens Gasket (each) Mk 7, Mk 8, Some Mk 9	\$ 7.45	RP	Taillight Lens Gasket, Long (each) 60-67 Mk 2, Mk 9	\$ 9.85
----	---	---------	----	--	---------

LIGHT PADS

RN	Taillight Mounting Pad Mk 7, Mk 8, Some Mk 9	\$ 6.60	RO	Front Directional Mounting Pad Mk 7, Mk 8, Mk 9, Mk 2	\$ 6.25
RQ	Headlight Mounting Pad, Mk 4	\$ 9.00	R4	Inner Headlight Dust Excluder Mk 8, Mk 9	\$ 14.80
R5	Headlight Dust Excluder, Mk 5, Mk 7	\$ 8.05	R45	Headlight Dust Excluder, Bucket to Body Mk 8, Mk 9	\$ 8.35
R154	Reverse Light Lens Gasket Mk 7, Mk 8, Mk 9	\$ 7.45	R101L	Taillight Mounting Pad, passenger side	\$ 13.80
R101R	Taillight Mounting Pad, driver's side Mk 2	\$ 13.80	R105	Headlight Dust Excluder, Mk 2	\$ 16.80
R168	"O Ring Seal" for sidelights (each) This is for welded on only (2 required) Mk 7, Mk 8, Mk 9	\$ 3.25	RS	Sidemarket Light Mounting Pad. Fits all XJ Sedans, front or rear	\$ 8.00

MOUNTS

R38	Rear Motor Mount (each) (2 required) Mk 5, Mk 2 with auto trans	\$ 14.95	R125	Front Motor Mount (each) (2 req) Mk 5	\$ 31.05
R39	Motor Mount (each) Fits Mk 9 rear(2 req) Fits front on Mk 1, Mk 2, 3.4S, 3.8S, 420, 420G (2 req on all) original shape with 7/16" fine threads	\$ 16.00	R39A	Front Motor Mount (each) (2 req) Mk 10	\$ 13.35
R39B	Front Motor Mount (each) (2 req) Mk 7, Mk 8, Mk 9	\$ 16.75	R39	Rear Bumper Mount (each) (4 req) original shape with 7/16" fine threads. Mk 1, Mk 2, 420	\$ 16.00
R122	Front Subframe Mount (each) (2 req) Mk 2, 3.4S, 3.8S, 420	\$ 24.95	R127	Radiator Mount Insulating Rubbers (each) Mk 1, Mk 2, 3.4S, 420, 420G, Mk 10 (4 required on all)	\$ 3.25
R135	Rear Transmission Mount. Triangle shaped, fits all models with overdrive	\$ 18.75	R136	Rear Transmission Mount Set, XJS. Set of two rubber spring collars	\$ 13.20
R136A	Rear Transmission Mount Set. Fits Mk 2 with standard trans and O.D.	\$ 17.65	R136B	Rear Transmission Mount Set. Contains 2 spring collars and the center bushing. Fits XJ 6 and XJ 12, Series I and II	\$ 26.75
R136C	Rear Transmission Mount Bushing. Fits XJ6 and XJ12, Series III	\$ 15.00			

PEDAL PADS

RA	Clutch and Brake Pedal Pads (each) Mk 5, Mk 7, Mk 8, Mk 9	\$ 11.95	R150	Brake and Clutch Pedal Pads (each) with "J" emblem in pad. Mk 1, Mk 2, Mk 10, 420, 420G	\$ 12.00
RB	Accelerator Pedal Pad Mk 5, Mk 7, Mk 8, Mk 9	\$ 11.95	RD	Accelerator Pedal Pad—Mk 10, Mk 1, Mk 2, 420, 420G, 3.4S, 3.8S	\$ 16.00
RE	Brake Pedal Pad for Automatic Trans equipped cars. Mk 7, Mk 8, Mk 9, Mk 10, Mk 1, Mk 2, 3.4S, 3.8S, 420, 420G, XJ6	\$ 16.00			

WINDSHIELD & WIPERS

R21	Wheel Box Mounting Pad (each) Goes un- der chrome windshield wiper bezel Mk 8, Mk 9, Mk 2	\$ 1.45	R29	Windshield Wiper Shaft Grommet Mk 5	\$ 4.15
R50	Windshield Washer Squirter Pad (each) (2 req) Mk 7, Mk 8, Mk 9, Mk 2	\$.85	R123	Windshield Wiper Motor Mount, Mk 5—Triangle metalastic 3 studded mount	\$ 29.59

MISCELLANEOUS

R6	Jack Securing Rubber Cup, Mk 5	\$ 14.95	R8	Jacking Hole Plug (each) Mk 5, Mk 7, Mk 8, Mk 9 front	\$ 9.85
R14	Angled Jacking Hole Plug (each) Mk 9 side, Mk 10	\$ 18.00	R132	Shift Lever Mounting Bushing (each) (2 req) Mk 5, Mk 7, Mk 8, Mk 9, Mk 1, Mk 2	\$ 3.85
R157	Upper Bumper Stops, XJ6, XJS	\$ 9.36	R159	Rear Bumper Stops—All IRS Models	\$ 15.00
R163	Door Buffers, Mk 2 (each) (6 for hood, 4 for door)	\$ 1.68			

WEATHERSTRIPPING

We have provided the correct lengths of weatherstripping for each given model of car where applicable. If you do not need a complete set, weatherstripping can be purchased by the foot. Please inquire for prices.

DOORS & SILLS

R64LF	Door Sealing Rubber Kit, Left Front	\$102.00	R64LR	Door Sealing Rubber Kit, Left Rear	\$102.00
R64RF	Door Sealing Rubber Kit, Right Front	\$102.00	R64RR	Door Sealing Rubber Kit, Right Rear	\$102.00
				Fits MK 2, 3.4S, 3.8S	
R226	Door Rubber, Left Front	\$ 90.00	R227	Door Rubber, Left Rear	\$ 90.00
R228	Door Rubber, Right Front	\$ 90.00	R229	Door Rubber, Right Rear	\$ 90.00
				Fits 420G	
R92C	Windlacing Rubber (52 ft) Mk7, Mk 8, Mk9	\$105.60			
R200	Front Door Seal, Passenger Side	\$120.00	R202	Rear Door Seal, Passenger Side	\$120.00
R201	Front Door Seal, Driver's Side	\$120.00	R203	Rear Door Seal, Driver's Side	\$120.00
	XJ6 & XJ12, Series I, & II			XJ6 & XJ12, Series I & II, Short Wheelbase	

GROMMETS

R205 Rear Door Seal, Driver's Side \$110.00
XJ6 & XJ12 Series I & II—Long Wheel-
base

This listing consists of various grommets available for the different sedan models. These grommets are available individually or you can purchase the grommet kits. The kits contain the required number of grommets to do one car and are offered at a discounted price.

INDIVIDUAL GROMMETS—MARK 5

R204 Rear Door Seal, Passenger Side \$110.00

R28 Grommet, Firewall (each) (1 req) \$ 6.25
Oil and temperature lines

R206 Front Door Seal, Passenger Side \$ 75.00

GR1 Grommet, Tool Compartment Light Wires \$ 2.75

R207 Front Door Seal, Driver's Side \$ 75.00

GR3 Grommet, Body Harness (each) (2 req) located in firewall \$ 3.00
above trans. tunnel

R208 Rear Door Seal, Passenger Side \$ 85.00

R209 Rear Door Seal, Driver's Side \$ 85.00
XJ6 Series III

GR4 Grommet (each) (3 req) Instrument panel wiring harness \$ 3.00
main wiring harness in front crossmember

R210 Door Seal, Passenger Side, XJS \$ 87.50

GR6 Grommet (each) (10 req) Fuel lines, brake lines, defroster \$ 3.60
ducts

R211 Door Seal, Driver's Side, XJS \$ 87.50

GR7 Grommet (each) (4 req) Taillight harness \$ 3.00

HOOD

GR9 Grommet (each) (5 req) Fuse box harnesses, headlight \$ 3.15
bucket harnesses, bottom firewall wiring harness

R223 Rear Hood Seal, XJ6, XJ12 \$ 15.00

R224 Side Hood Seals (pair), XJ6, XJ12 \$ 7.50

GR10 Grommet, Sidelamps (each) (2 required) \$ 2.90

R225 Front Hood Seals, XJ6, XJ12 \$ 18.50

GR11 Grommet, (each)(2 req)Wiring harness thru firewall \$ 4.25

SUNROOF

GR13 Grommet (each) (3 req) Windshield wiper cable, speedome- \$ 1.90
ter cable, parking brake cable

R95 Sunroof Rubber, Mk 7, Mk 8, Mk 9 \$ 9.00

TRUNK

GR17 Grommet (each) (9 req) Horn & Light wiring harnesses, \$ 3.05
spare tire compartment harnesses, glove box

R91 Trunk Rubber Set, Mk 2, 420G \$ 36.60

GR18 Grommet, Heater Control Rod, located in firewall \$ 2.90

R103 Trunk Rubber Set \$ 30.00
Mk 7, Mk 8, Mk 9

MARK 7

R220 Trunk Seal, XJ6, XJ12 \$ 37.50

GR1 Grommet (4 req), Fuel pump mounting \$ 2.75

R221 Trunk Seal, XJS \$ 37.50

GR2 Grommet (3 req), Fuel pump harness \$ 2.90

WINDOWS

GR3 Grommet, Body harness \$ 3.00

R96B Rear Vent Window Rubber, Mk 2 \$ 14.65

GR4 Grommet, Reverse switch wires \$ 3.00

R96C Rear Vent Window Rubber, Mk 7, Mk 8 \$ 21.60
Mk 9, Mk 10

GR6 Grommet (10 req) Fuel pump lines, inner fender splash pan- \$ 3.60
els, brake lines, brake suction line, fuel pump harness

R230 Vent Window Seal, XJS (2 required) \$ 10.00

GR7 Grommet (4 req) Trunk lid harness, hood release cable, \$ 3.00
heater tap control, speedometer cable

R231 Quarter Glass Seal, Passenger Side \$ 57.50

GR8 Grommet (each) (5 req) Body harness, tachometer cable, \$ 3.10
fuel lines, heater casing

R232 Quarter Glass Seal, Driver's Side, XJS \$ 57.50

GR9 Grommet (each) (3 req) Main panel harness in cowl, head- \$ 3.15
light bucket harnesses

MISCELLANEOUS

R68A License Plate Panel Rubber, Mk 5 \$ 8.50

GR10 Grommet, Sidelamps (each) (2 required) \$ 2.90

R69A Fender Skirt Rubber Set, Mk 5 \$ 9.25

R70 Transmission Tunnel Cover Seal, Mk 5 \$ 7.85

R98 Running Board Rubber (ft) \$ 2.55
Mk 4, & SS100, as required

MARK 8

GR1	Grommet (each) (4 req) Fuel Pump Mounting	\$ 2.75
GR2	Grommet (each) (7 req) Fuel Pump harness, fuel tank vent, rear tonneaus stiffener	\$ 2.90
GR3	Grommet, Body Harness	\$ 3.00
GR4	Grommet, Reverse Switch Wires	\$ 3.00
GR6	Grommet (each) (8 req) Fuel pump lines, inner fender splash panels, brake lines, brake suction line, fuel pump harness	\$ 3.60
GR7	Grommet (each) (6 req) Trunk lid harness hood release cable, heater tap control, speedometer cable, windshield washer	\$ 3.00
GR8	Grommet (each) (5 req) Body harness, tachometer cable, fuel lines, heater casing	\$ 3.10
GR9	Grommet (each) (3 req) Main panel harness in cowl, headlight bucket harnesses	\$ 3.15
GR10	Grommet, Sidelamps (each) (2 req)	\$ 2.90
GR11	Grommet, Tachometer Cable	\$ 4.25

MARK 9

GR1	Grommet (each) (5 req) Fuel pump mounting, bench seat harness	\$ 2.75
GR2	Grommet (each) (8 req) Fuel pump harness, fuel tank vent, rear tonneaus stiffener, handbrake	\$ 2.90
GR3	Grommet (each) (2 req) Inner fender splash panel, seat base support (for body harness)	\$ 3.00
GR4	Grommet, Reverse Switch Wires	\$ 3.00
GR6	Grommet (each) (9 req) Fuel pump lines, inner fender splash panels, brake lines, power steering hose	\$ 3.60
GR7	Grommet (each) (7 req) Trunk lid harness, hood release cable, heater tap control, speedometer cable, windshield washer, heater case	\$ 3.00
GR8	Grommet (each) (5 req) Body harness, wiper harness, tachometer generator harness, fuel lines in trunk	\$ 3.10
GR9	Grommet (each) (3 req) Main panel harness in cowl, headlight bucket harnesses	\$ 3.15
GR10	Grommet, Sidelamps (each) (2 req)	\$ 2.90
GR11	Grommet, Wiper Motor Housing	\$ 4.25

MARK 1—LATE 2.4

GR1	Grommet, Dash Panel for L.H. Harness	\$ 2.75
GR2	Grommet, Heater Lid for outlet pipe	\$ 2.90
GR4	Grommet (each) (4 req) For body harness at rear of body	\$ 3.00
GR6	Grommet, Forward Harness	\$ 3.60
GR7	Grommet (each) (11 req for R.H. Drive cars)(12 req for L.H. Drive Cars). Windshield washer tubes, speedometer cable, hood cable, windshield wiper cable, dimmer switch cable, fuel tank cable, trunk lid cable, door switches, brake lines	\$ 3.00
GR8	Grommet, Fuel Line	\$ 3.10
GR9	Grommet (each) (4 req) Headlight bucket cables, fuel line, chassis harness	\$ 3.15
GR11	Grommet (each) (2 req) Tachometer cable, w/wiper motor Grommets not currently available—w/wiper motor bracket (3)	\$ 4.25

MARK 1—3.4

R28	Grommet, Firewall (each) (1 req) Oil and temperature lines	\$ 6.25
GR1	Grommet, Dash Panel for L.H. Harness	\$ 2.75
GR2	Grommet, Heater Lid, for outer pipe	\$ 2.90
GR4	Grommet (each) (4 req) for body harness at the rear of the body	\$ 3.00
GR6	Grommet, Forward Harness	\$ 3.60
GR7	Grommet (each) (12 req for R.H. Drive cars)(13 req for L.H. Drive Cars). Windshield washer tubes, speedometer cable, hood cable, windshield wiper cable, dimmer switch cable, fuel tank cable, trunk lid cable, door switches, brake lines	\$ 3.00
GR8	Grommet, Fuel Line	\$ 3.10
GR9	Grommet (each) (4 req) Headlight bucket cables, fuel line, chassis harness	\$ 3.15
GR11	Grommet, Windshield Wiper Motor	\$ 4.25

Grommets not currently available: Windshield wiper motor bracket (3) Firewall grommet for tachometer cable

MARK 2

GR1	Grommet, Center Pillar (each) (2 req)	\$ 2.75
GR2	Grommet, Center Pillar (each) (2 req). Also re- quired one additional grommet for steering col- umn lock connector cable when so equipped	\$ 2.90
GR4	Grommet (each) (2 req) For body harness at the rear of the body	\$ 3.00
GR6	Grommet, Forward Harness	\$ 3.60
GR7	Grommet (each) (12 req for R.H. drive cars)(13 req for L.H. drive cars) windshield washer tubes, speedometer cable, hood cable, windshield wiper cable, dimmer switch cable, fuel tank cable, trunk lid cable, door switches, brake lines and side lamps.	\$ 3.00
GR8	Grommet, body harness (each) 4 required for R.H. drive cars (1 for dimmer switch) 3 required for L.H. drive cars	\$ 3.10
GR9	Grommet (each) (2 req) Headlight bucket cables	\$ 3.15
GR10	Grommet, Heater Control (each) (2 req)	\$ 2.90
GR11	Grommet, Windshield Wiper Motor Grommets not currently available: body harness through sills (4) Fuel pump mounting (2) Fuel line through trunk floor (1)	\$ 4.25

MARK 10—3.8

GR3	Grommet (each) (2 req) License Plate Harness	\$ 3.00
GR4	Grommet (each) (5 req) Body harness in seat back, fuel non-return valve	\$ 3.00
GR7	Grommet (each) (8 req) Windshield washer tubing in bulkhead, license plate harness, trans harness, brake lines, hood release cable	\$ 3.00
GR8	Grommet, Speedometer Cable	\$ 3.10
GR11	Grommet, Wiper Motor Housing	\$ 4.25
GR13	Grommet (each) (3 req) Interior light cables	\$ 1.90
GR15	Grommet (each) (2 req) Front door switches at "A" post	\$ 1.35
GR17	Grommet, R.H. Engine Harness in air filter box	\$ 3.05
Grommets not currently available: Vent pipe in trunk (1) R.H. engine harness at air filter box (1) Battery carrier holes in wheel arch (2) Headlight buckets wires (2) Fuel pump harness in trunk (1) Overdrive solenoid shield (1)		

MARK 10—4.2

GR3	Grommet (each) (2 req)	\$ 3.00
GR4	Grommet (each) (4 req) Body harness in seat back	\$ 3.00
GR7	Grommet (each) (10 req) Windshield washer tubing in bulkhead license plate harness, trans harness, hood release cable, heater cable in parcel tray, re- verse switch cable, brake lines in front wheel arches	\$ 3.00
GR8	Grommet, Speedometer Cable	\$ 3.10
GR11	Grommet, Wiper Motor Housing	\$ 4.25
GR13	Grommet, (each) (3 req) Interior light cables	\$ 1.90
GR15	Grommet (each) (2 req) Front door switches at "A" post	\$ 1.35
GR17	Grommet (each) (2 req) R.H. engine harness in air filter box, terminal post harness	\$ 3.05
Grommets not currently available: Vent pipe in trunk (1) R.H. engine harness at air filter box (1) Body harness at seat pan (1) Battery carrier holes in wheel arch (2) Headlight buckets wire (2) Fuel pump harness in trunk (1) Overdrive solenoid shield (1) Driveshaft center bearing mount (4)		

RUBBER GROMMET KITS

GP15	Complete Grommet Kit, Mark 5	\$114.00
GP4	Complete Grommet Kit, Mark 7	\$ 86.65
GP5	Complete Grommet Kit, Mark 8	\$ 98.75
GP6	Complete Grommet Kit, Mark 9	\$111.40
GP21	Complete Grommet Kit, Mk 1 (late 2.4)	\$ 70.75
GP22	Complete Grommet Kit, 3.4 Mk 1	\$ 69.65
GP23	Complete Grommet Kit, Mk 2	\$ 70.75
GP24	Complete Grommet Kit, 3.8 Mk 10	\$ 52.20
GP25	Complete Grommet Kit, 4.2 Mk 10	\$ 57.10

WINDOWS**WINDSHIELD SEALS**

W7	Windshield Seal, Mk 1	\$ 90.00
W8	Windshield Seal, Mk 8, Mk 9	\$110.00
W9	Windshield Seal, Mk 2, 3.4S, 3.8S	\$ 70.00
W10	Windshield Seal, XJ6 & 12, Series I & II	\$ 90.00
W11	Windshield Seal, XJS	\$125.00
WLB	Windshield Seal Lockbead Fits all of the above windshield seals	\$ 14.95

BACKLIGHT SEALS

RWS4	Back Window Seal, Mk 1	\$110.00
RWS5	Back Window Seal, Mk 2, 3.4S, 3.8S	\$ 55.00
RWS6	Back Window Seal, Mk 7, Mk 8, Mk 9	CALL
RWS10	Back Window Seal, XJ6 & 12 Series I & II	\$ 80.00
RWS11	Back Window Seal, XJS	\$ 50.00

WINDOW SCRAPERS

These are the fuzzy and rubber strips that are located along the inside top of the doors. Their purpose is to remove the dust and water as the windows are rolled up and down.

WS7	Fuzzy Felt Window Scrapers (pair) Mk 7, Mk 8, Mk 9, Mk 10 2 pairs required to do all 4 doors	\$ 12.50
WS11	Fuzzy Felt Window Scrapers (pair) Mk 2 2 pairs required to do all 4 doors	\$ 12.00

WINDOW CHANNEL FELT

Window channel felt is used on the vertical channels that the side window glass rides in. It is also used on the top of the window frame on some models. This felt has an adhesive on the back for ease of installation.

WCF	Window Channel Felt (per foot) Mk 9 uses 28 feet	\$ 1.00
-----	--	---------

WIPER BLADES

WW1	Wiper Blade, Mk 7 (each)	\$ 13.85
WW5	Wiper Blade, Mk 9 (each)	\$ 12.85

DEFROSTER HOSE

DVH	Defroster Vent Hose, 1-1/4" I.D.—As required, per foot	\$ 4.50
-----	--	---------

ELECTRICAL**BULLET CONNECTORS**

ER	Single Bullet Connectors (each)	\$ 1.10
ES	Double Bullet Connectors (each)	\$ 1.80
EU	Five Way Bullet Connectors (each)	\$ 9.25
EU1	Five Way Bullet Connector Bracket	\$ 2.30
E50	Male Bullet Connector (10 pack)	\$ 4.25

IGNITION PARTS—Please note: all ignition parts supplied are Lucas manufactured with the exception of items they no longer supply.

WH14	Spark Plug Wire Set, Mk 5	\$ 43.00
WH15	Spark Plug Wire Set, Fits early Mk 7 with the flat distributor cap	\$ 62.05
WH8	Spark Plug Wire Set, Fits later Mk 7, Mk 8, Mk 9, Mk 10, Mk 1, Mk 2, 3.4S, 3.8S	\$ 51.35
Spark plug wires are black wire braided and lacquered as original with soldered distributor connections for the earlier cars. These earlier wire sets do not include the spark plug terminals (EJ) but do come with the distributor and coil nuts.		
EJ	Spark Plug Terminals (each) (6 req) Fits WH14, WH15, WH8	\$ 12.00
E51	Spark Plug Wire Separator (each) Thin, brown bakelite (3 req)	\$ 5.35
E52	Spark Plug Wire Separate (each) Thick, brown bakelite (2 req)	\$ 5.35
EL	Spark Plum Loom-We have fabricated this out of aluminum so it lasts longer than the molded paper ones.	\$ 44.75
WH20	Custom Wire Set, XK6-Constructed of solid-core Lucas racing wire with resistor ends. This set will never wear out and it won't affect your radio	\$ 80.00

WH13	Spark Plug Wire Set, all V-12	\$ 27.80	EG	Condensator, Mk 4, Mk 5, Mk 7	\$ 25.70
EQ	“Champion” Spark Plugs (pkg of 6) Fits 3.4, 3.8, all 4.2 with fuel injection	\$ 21.00	EF	Condensator, Mk 1, Mk 2, Mk 8, Mk 9, 3.8, Mk 10	\$ 4.25
			C32354	Ignition Wire Separating Disc (each) XJ’s & XJ12 (5 req)	\$ 2.75
EQ11	“Champion” Spark Plugs (pkg of 6) Fits all 4.2 with carburetors	\$ 19.80		DISTRIBUTORS	
			E103	4.2 Mk 10, 420, 420G—automatic transmission only	\$275.00
EQ9	“Champion” Spark Plugs (pkg of 12) Fits all 5.3	\$ 39.60	E104	3.4 and 3.8 motors with 9:1 compression and dual carbs 3.4S, 3.8S, 3.8 Mk 2	\$275.00
EQ5	“Champion” Spark Plugs (pkg of 12) Fits all 5.3 “HE” motors	\$ 30.00	E105	56-60 Mk 2 with 2.4L 8:1 compression motor	\$275.00
			E106	59-60 Mk 9 with 9:1 compression Mk 1, Mk 7, Mk 8	\$275.00
EA	Distributor Cap, Mk 4, Mk 5, Mk 7	\$ 67.80	E107	Mk 1, Mk 7, Mk 8—54-58 standard trans with 3 1/2 L motor	\$275.00
EA1	Distributor Cap, Screw in Terminals Mk 1, Mk 8, Mk 9	\$ 36.90	E108	61-65 3.4 and 3.8 with 7:1 or 8:1 comp	\$275.00
			E109	1970 XJ6	\$275.00
E5	Distributor Cap, Screw in Terminals, Mk 2, Mk 10 and all 4.2 motors to 1971	\$ 17.10		DISTRIBUTOR COMPONENTS	
			E80	Distributor Micro Housing Mk 4, Mk 5, Mk 7	\$ 48.15
EC	Distributor Cap, 72-74 XJ6	\$ 16.00	E81	Distributor Cap Hold-down Clips Mk 4, Mk 5, Mk 7, Mk 8	\$ 5.00
E40	Distributor Cap, Clip Down Style 75-84 XJ6	\$ 12.00	E82	Distributor Cam Mk 4, Mk 5, Mk 7	\$ 26.25
			E83	Distributor Cam, Large Diameter. Used on some distributors From 1957-63	\$ 26.25
E41	Distributor Cap, Screw Down Style 80-84 XJ6, 84 XJS	\$ 27.00	E85	Low Tension Lead (for 2 piece dist.) Mk 4, Mk 5, Mk 7, Mk 8	\$ 4.25
E2	Distributor Cap, V-12, all models	\$ 58.85	E86	Contact Breaker Base Plate, Mk 8, Mk 9, Mk 1, Mk 2, 3.8, Mk 10	\$ 21.40
EH	Plastic Distributor Cap & Coil Nuts	\$ 1.20	E87	Contact Breaker Base Plate, Mk 4, Mk 5, Mk 7	\$ 21.40
ED	Rotor, Mk 4, Mk 5, Mk 7	\$ 14.13	E88A	Distributor Shaft and Action Plate—14 degree for Mk 7	\$ 32.10
ED1	Rotor, Mk 1, Mk 2, Mk 8, Mk 9, Mk 10, 3.4S, 3.8S, 420, 420G, XJ6 to 1974	\$ 4.25	E88B	Distributor Shaft and Action Plate—15 degree for Mk 7	\$ 32.10
			E88C	Distributor Shaft and Action Plate—17 degree for Mk 7	\$ 32.10
E47	Rotor, Centrifugal Cutout Style, Mk 10, 420, 420G, XJ6 to 71	\$ 59.90	E89	Distributor Clamping Plate—3.4, 3.8, 4.2	\$ 5.00
			ELB30	Distributor Bushing, 1947 3 1/2L Mk 4	\$ 2.30
E43	Rotor, 75-79 XJ6	\$ 3.25	ELB33	Distributor Bearing—all motors 1949-62	\$ 6.25
E46	Rotor, 80-84 XJ6	\$ 7.00		FUSES AND FUSE BOXES	
E1	Rotor, XJS 1980 on (also replaces rotors with black bushes or ones made of blue epoxy)	\$ 33.20	EM	Fuse Box, Mk 5, Mk 7	\$131.45
			EO	Fuse Box, Mk 8 (small fuse box, Mk 9)	\$ 32.10
E44	Rotor, V-12, black with green stripe, XJ12, 1975-79, XJS 1976-79 with Lucas triggering electronics	\$ 57.00	EN	Large Fuse Box, Mk 9	\$101.50
			E9	Fuse Box—the common 2 fuse type with snap-on lid Fits Mk 2, Mk 10, 420’s, and others	\$ 26.10
E45	Rotor, V-12, with red rubber bushes, XJ12 1973 on, XJS 1976 on with “Hall Effect” triggering electronics	\$ 52.00	EW	35 amp Lucas Fuse (each)	\$.95
EE	Points, Mk 4, Mk 5, Mk 7	\$ 18.00	EX	50 amp Lucas Fuse (each)	\$.95
EE1	Points, Mk 1, Mk 2, Mk 8, Mk 9, 3.8, Mk 10	\$ 11.80	18		

GENERATOR COMPONENTS

ELB20	Rear Generator Bearing	\$ 15.35
ELB21	Front Generator Bearing (pulley end)	\$ 8.00
ELB40	Generator Brushes	\$ 6.00

MISCELLANEOUS ELECTRICAL ITEMS

E6	Spark Plug Wire End Terminal Mk 4, SS100	\$ 3.50
E10	Coil (replacement) does not have screw in center terminal. For all cars with point type distributors	\$ 33.20
E11	Electric Tach Generator	\$291.50
ECB1	Electric Clock Battery-Fits all cars with battery powered clock	\$ 5.75
EVR1	Voltage Regulator, Mk 9. This is a Lucas replacement for the original unit. It has a plastic case instead of the original aluminum one.	\$ 42.45
EVR9	Voltage Regulator Mk 10, 420, 420G, 69-70 XJ6	\$ 82.40
EVR10	Voltage Regulator, Lucas replacement 70-71 XJ6 with Butec alternator	\$ 39.60
EV	Lucas Light Unit Bulb Holder Socket For PF 770 and non-sealed beams	\$ 14.10
E19	Split Push Connector for Wire Ends	\$.95
E28	Turn Signal Flasher Unit (3 prong) Mk 1, Mk 2, Mk 7, Mk 8, Mk 9, Mk 10, 420, 420G	\$ 33.20
E31	Turn Signal Flasher Unit Fits all late models with 2 prong flasher	\$ 9.00

INDIVIDUAL "JEWELS" AND BEZELS

MARK 7		
C4629	Bezel for Ignition Switch (presently not available)	*****
C4628	Bezel for Road Lights Switch (med blk)	\$ 7.00
C4631	Bezel for Cigar Lighter (x-large)	\$ 7.25
C2769	Bezel for Remaining Switches (small) (each 7 required)	\$ 7.25
C2755	Ignition "Jewel" Warning Light (red)	\$ 12.85
C4617	Traffic "Jewel" Warning Light (amber)	\$ 12.85
C4617G	Turn Indicator Warning Light (green)	\$ 12.00
MARK 8		
C4630	Bezel for Starter Switch (medium)	\$ 7.25
C4628	Bezel for Road Lights Switch (med blk)	\$ 7.00
C4631	Bezel for Cigar Lighter (x-large)	\$ 7.25
C2769	Bezel for Remaining Switches (small) (each) (7 required)	\$ 7.25
C2755	Ignition "Jewel" Warning Light (red)	\$ 12.85
C4617	Traffic "Jewel" Warning Light (amber)	\$ 12.85
C4617G	Turn Indicator Warning Light (green)	\$ 12.00
MARK 9		
C4629	Bezel for Ignition Switch (presently not available)	*****
C4630	Bezel for Starter Switch (medium)	\$ 7.25
C4628	Bezel for Road Lights Switch (med blk)	\$ 7.00
C4631	Bezel for Cigar Lighter (x-large)	\$ 7.25
C2769	Bezel for Remaining Switches (small) (each) (7 required)	\$ 7.25
C2755	Ignition "Jewel" Warning Light (red)	\$ 12.85
C4617	Traffic "Jewel" Warning Light (amber)	\$ 12.85
C4617G	Turn Indicator Warning Light (green)	\$ 12.00

"JEWEL" AND BEZEL SETS

E90H	High Note Horn	\$ 39.95	JBKIT7	Mark 7 "Jewel" and Bezel Set (11 pieces)	\$120.80
E90L	Low Note Horn	\$ 39.95	JBKIT8	Mark 8 "Jewel" and Bezel Set (12 pieces)	\$128.70
	Nice replacements for the originals on the early sedans		JBKIT9	Mark 9 "Jewel" and Bezel Set (12 pieces)	\$128.70

Relays—We stock a large number of different Lucas relays. To simplify correct ordering, please supply us with the original 5 digit Lucas part number on the side of the relay if at all possible.

SWITCH KNOBS

E13A	Panel/Int. Knob—Mk 7, Mk 8, Mk 9	\$ 8.50
E15	Heater Control Knob	\$ 10.25
E15A	Panel Dimming Knob	\$ 10.25
E17	Lighter Knob	\$ 9.25
E18	Fog Light Switch Button	\$ 5.00
E20	Wiper Knob, Single Speed—Mk 7	\$ 6.75
E21	Wiper Knob, Two Speed—Mk 7, Mk 8, Mk 9	\$ 6.75

E22A	Starter Button Knob, Long Mk 7, Mk 8, Mk 9	\$ 9.25	LL7	Front Directional Light Assembly, complete with wires and rubber pad. Mk 8, Mk 9	\$ 89.25
E32	Fan Knob, Mk 7, Mk 8, Mk 9	\$ 8.50	LL13	Red Fender Medallion with Clip (each)(2 req) Mk 7, Mk 8, Mk9	\$ 4.25
E33	Map Knob, Mk 7, Mk 8, Mk 9	\$ 8.50	BDB26	Boot Lamp Assembly, Mk 5—complete with lens, rim, bulb and bulb holder	\$ 40.65
E34	Petrol L/R Knob, Mk 7, Mk 8, Mk 9	\$ 10.00			
JC9	Original Style Shift Knob, black knob with shift pattern. Mk 7, Mk 8, Mk 9	\$ 17.10	MARK 8		
			LL10	Taillight Lens	\$ 19.20
JC9A	Jam Nut, Stainless, used for positioning shift knob	\$ 1.50	LL27	Reverse Light Lens	\$ 16.00
			MARK 9		
	SWITCHES		LL17A	Lower Taillight Lens (red)	\$ 26.75
E4	Fog or Electric Choke Switch	\$ 64.95	LL17B	Upper Taillight Lens (amber)	\$ 26.75
SW34382	Headlight Switch (61-67) Mk 2, 3.4S, 3.8S	\$ 50.00	LL17C	Chrome Clip Between LL17A and LL17B	\$ 7.75
			LL19	Round Taillight Reflector	\$ 11.80
SW76605	Battery Cutoff Switch (accessory)	\$ 67.40	LL27	Reverse Light Lens	\$ 16.00
SW3	Windshield Wiper Switch Mk 7, Mk 8, Mk 9, Mk 1	\$101.50	MARK 2		
			LL17A	Lower Taillight Lens (red)	\$ 26.75
SW4	Heater Rheostat Switch (replacement) Mk 7, Mk 8, Mk 9	\$ 85.50	LL17B	Upper Taillight Lens (amber)	\$ 26.75
			LL17C	Chrome Clip Between LL17A and LL17B	\$ 7.75
SW5	Headlight Dimmer Switch Mk 7, Mk 8, Mk 9	\$ 53.50	LL19	Round Taillight Reflector	\$ 11.80
			XJ6, XJ 12		
SW7	Ignition Switch (electrical part) Mk 7, Mk 8, Mk 9	\$ 38.50	LL23L	Front Directional Lens, 1969-73	\$ 23.00
			LL23R	Front Directional Lens, 1969-73	\$ 26.75
E30	Ignition Lock and Key—Fits SW7 and other dash mounted switches	\$ 18.95	LL51L	Front Directional Lens, 1974	\$ 68.87
			LL51R	Front Directional Lens, 1974	\$ 68.87
SW20	Starter Switch—Mk 7, Mk 8, Mk 9	\$ 74.90	LL52	Front Directional Lens, 1975-79	\$ 20.00
	We stock a large number of different Lucas switches. To simplify correct ordering, please supply us with the 5-digit Lucas part number on the side of the switch, if at all possible.		LL57L	Front Side Marker Lens, 1969-83	\$ 12.00
			LL57R	Front Side Marker Lens, 1969-83	\$ 12.00
	LIGHTS AND LENSES		LL25L	Rear Side Marker Lens, 1969-83	\$ 28.90
	XJ6, XJ12, XJS				
LL2	License Plate/Reverse Light (each) (2 req) Mk 5	\$250.00	LL25R	Rear Side Marker Lens, 1969-83	\$ 28.90
			LL63L	Taillight Lens, 1969-73	\$ 26.56
LL4	Side Lamp Unit (each)(2 req). This is the electrical part with the chrome trim and the glass lens. Mk 5, Mk 7, Mk 8, Mk 9	\$ 85.90	LL63R	Taillight Lens, 1969-73	\$ 26.56
			LL66L	Taillight Lens, 1974-79	\$ 80.00
LL6A	Side Lamp Unit (each)(2 req) This is the electrical part with the chrome trim and the glass lens. It is genuine Lucas and has the correct lettering on the lens. Fits Mk 2, 3.4S, 3.8S	\$ 50.85	LL66R	Taillight Lens, 1974-79	\$ 80.00
			LL67L	Taillight Lens, 1980-82	\$ 85.00
			LL67R	Taillight Lens, 1980-82	\$ 85.00

LL71L	Reverse Light Lens, 1969-70	\$ 13.66	BB6	Combination front turn/parking lights 1971-1973, 1975-on	\$ 1.65
LL71R	Reverse Light Lens, 1969-70	\$ 15.88	BB9	Front side marker lights, all rear side marker lights, 1969-1977. License plate light, 1969-1973 and Trunk Light	\$ 1.75
LL72	Reverse Light Lens, 1970-1979	\$ 32.00			
LL75	License Plate Light Lens, 1969-73	\$ 15.93	BB10	Rear side marker lights, 1978 on License plate light, XJ6 & XJ12, 1974 on	\$ 1.25
LL75A	Rim for LL75	\$ 60.70			
LL76	License Plate Light Lens, 1974-79	\$ 11.81	BB11	Stop lights, 1980 on	\$ 1.50
XJS			BB12	Reverse light (festoon bulb)	\$ 2.50
LL80	Front Turn Signal Lens, 1976-83	\$ 12.74		REBUILT GAUGES	
LL81L	Taillight Lens, 1976-82	\$163.00	GRS1	Rebuilt Speedometer	\$188.50
LL81R	Taillight Lens, 1976-82	\$163.00	GRS2	Rebuilt Tachometer	\$188.50
LL84L	Reverse Light Lens	\$ 34.00	GRS3	Rebuilt Safety Gauge (Oil & Temp)	\$253.50
LL84R	Reverse Light Lens	\$ 34.00	GRS4	Rebuilt Fuel Gauge	\$188.50
	HEADLIGHTS AND FOGLIGHTS		GRS5	Rebuilt Electric Clock	\$135.00
	Some of these are new old stock in the original Lucas boxes. These lamps come without bulbs. Others are reproductions of the originals and are supplied complete.		GRS6	Rebuilt Battery Clock	\$135.00
			GRS7	Rebuilt Ammeter	\$188.50
DL5	SLR 700 Driving Light Lens	\$ 58.85		BRAKE PARTS	
DL6	Lemans Headlight	\$ 64.20		BRAKE PADS	
DL7	P 700 Headlight (each) (sold in pairs)	\$170.50	BP8	Square Brake Pads, front set	\$ 25.70
BB3	Foglight Bulb	\$ 10.25	BP8M	Front Pads, Repco Metalmaster—3.4 Mk 1, Mk 2, 3.8 Mk 10	\$ 62.05
BB5	Headlite Bulb for P/PL700 headlites	\$ 14.45	BP46	Front Pads, Mk 9	\$ 35.00
DL10	Reproduction PF700 Headlights (pair) These have the tripod lines on the lens with a flat lens fact. Mk 7	\$143.75	BP47	Front Pads, 4.2 Mk 10, 420G	\$ 40.00
DL11	Reproduction "J" Headlights (pair) Mk 8, Mk 9	\$143.75	BP27	Front Pads, 3.4S, 3.8S	\$ 36.30
	BULBS		BP14	Front Pads, 420, 69-73 XJ6, 73 XJ12 Overall pad size 3 7/8 x 2 5/8	\$ 26.75
BB1	Screw-type instrument panel bulb	\$ 1.50	BP26	Front Pads, 73 on XJ6, XJ12, XJS Repco Metalmaster Brake Pads Overall pad size 4 3/4 x 2 3/4	\$ 45.00
BB2	Fender-mounted sidelamps. Front directional lights. Reverse lights	\$ 1.65	BP115	Front Pads, XJ40	\$185.00
BB4	Trunk lights and interior lights Festoon-type bulb	\$ 2.50	BP8	Square Brake Pads, rear set	\$ 25.70
BB6	Combination parking/turn lights Combination tail/stop lights	\$ 1.65	BP8M	Rear Pads, Repco Metalmaster 3.4 Mk 1, Mk 2, Mk 9, 3.8 Mk 10	\$ 62.05
BB9	License plate lights	\$ 1.75	BP27	Rear Pads, 4.2 Mk 10, 3.4S, 3.8S, 420G	\$ 36.30
			BP25	Rear Pads, 420, 69-72 XJ6	\$ 42.80
XJ6, XJ12, XJS			BP33	Rear Pads, Repco Metalmaster—72 on XJ6, XJ12, XJS	\$ 42.80
BB2	Directional Lights, rear Directional lights, front 1969, 1970, 1974	\$ 1.65	BP116	Rear Pads, XJ40	\$108.00

HANDBRAKE PADS

BP28	3.4 Mk 1, Mk 2—Linings must be riveted to original backings	\$ 96.00
BP29	Early Mk 9, Some Mk 2 Overall pad size 1 7/8" x 2"	\$ 50.00
BP30	All cars with I.R.S. Overall pad size 1 1/2" x 1 1/2"	\$ 32.10

BRAKE SHOES

RB1	Relined Brake Shoes (front or rear) 2.4 Mk 1, Mk 7, Mk 8 Your old shoes must be sent to us	\$210.00
BP77	Rear Brake Shoe Bee-hive Spring (each) (4 required)	\$ 14.25

BRAKE ROTORS

BR4	Front Disc, 3.4S, 3.8S, Mk 2	\$101.50
BR6	Front Disc, 420	\$170.50
BR8	Front Disc, XJ6 Series I 1969-73	\$ 65.00
BR7	Front Disc (Vented) XJ6 1974 on, XJ12, XJS	\$106.50
BR2	Rear Disc, Mk 9, 3.8 Mk 10	\$ 97.00
BR3	Rear Disc, 3.4S, 3.8S, 4.2 Mk 10	\$ 85.00
BR5	Rear Disc, 420, XJ6, XJ12, XJS	\$ 64.20
BR11	Rear Discs (sold only in pairs) Fits late XJ's with the Dana rear end	\$250.00

BRAKE MASTER CYLINDERS

BP104	Mk 7, Early Mk 8 with drum brakes and Standard transmission	\$350.00
BP105	Late Mk 8, Mk 9, with disc brakes. Front master cylinder 3.8 Mk 10	*****
BP92	Rear Master Cylinder, 3.8 Mk 10	\$190.00
BP106	4.2 Mk 10, 420G	\$350.00
BP108	3.4S, 3.8S, Mk 2	\$220.00
BP84	420	\$250.00
BP110	XJ6, XK12, 1969 to 9/73	\$325.00
BP111	XJ6, XJ12, 10/73 to 1977 all XJS	\$220.00
BP112	XJ6, XJ12, 1977 on	\$210.00
BP117	XJ40, 1988 on	\$216.00

BRAKE CALIPER ASSEMBLIES

BP78	Front Caliper Piston and Cylinder (each) (2 required per side) Fits 3.4 Mk 1, Mk 2, 3.8 Mk 10	\$149.00
BP79	Rear Caliper Piston and Cylinder (each) (2 required per side) Fits 3.4 Mk 1, Mk 2, 3.8 Mk 10	\$212.00

BRAKE CALIPER PISTONS

BP128	Front Caliper Piston, 3.4S, 3.8S	*****
BP129	Front Caliper Piston, 64-67 420G, 64-66 Mk 10	*****

CLUTCH MASTER CYLINDERS

Clutch master cylinders are no longer available for the Mk 7, Mk 8, and Mk 9, and the original will have to be rebuilt.

BP91	Clutch Master Cylinder, Mk 1, Mk 2, 3.8 Mk 10	\$ 98.00
BP122	Clutch Master Cylinder, 3.4S, 3.8S	\$210.00
BP123	Clutch Master Cylinder, 4.2 Mk 10	\$ 75.00
BP124	Clutch Master Cylinder, 420	\$100.00
BP127	Clutch Master Cylinder, 420G	\$ 75.00
BP125	Clutch Master Cylinder, XJ6 to 5/73	\$110.00

CLUTCH SLAVE CYLINDERS

BP87	Clutch Slave Cylinder, Mk 7, 8, 9	*****
BP89	Clutch Slave Cylinder, 4.2 Mk 10, Mk 2 late, 420, 420G	\$ 92.00
BP90	Clutch Slave Cylinder, Mk 1, early Mk 2, 3.8 Mk 10, Early 4.2 Mk 10, 3.4S, 3.8S	\$105.95
BP126	Clutch Slave Cylinder, XJ6 to 5/73	\$ 70.00

POWER BRAKE SERVO UNIT

BP70	Air Reservoir Tank for Servo Unit, Mk 2, 3.4S, 3.8S	\$133.00
------	---	----------

BRAKE REBUILD KITS

BP12	Front Wheel Cylinder Kit, Mk 7, Mk 8	\$ 29.00
BP11	Rear Wheel Cylinder Kit, Mk 7, Mk 8	\$ 27.50
BP69	Rear Wheel Cylinder Kit, Later Mk 5	\$ 22.50
BP13	Master Cylinder Kit, Mk 4, Mk 5	\$ 30.00
BP62	Master Cylinder Kit, Mk 7 and Mk 8 with drum brakes	\$ 25.00
BP19	Master Cylinder Kit, all XJ's to 9/73	\$ 40.50
BP21	Master Cylinder Kit, XJ6, XJ12, XJS, 10/73 to 77	\$ 46.50
BP20	Master Cylinder Kit, 420	\$ 36.65
BP58	Master Cylinder Kit, 3.8 Mk 10, Mk 8 and Mk 9 with disc brake	\$ 40.65
BP60	Master Cylinder Kit, 4.2 Mk 10, 420G	\$ 40.00
BP63	Master Cylinder Kit, Mk 2, 3.4S, 3.8S	\$ 35.00
BP88	Master Cylinder Kit, Mk 1	\$ 35.00

BP97	Master Cylinder Kit, XJ6, XJ12, 1977 on	\$ 35.00	BP93	Servo Kit, 420	\$ 63.90
BP98	Master Cylinder Kit, XJS 1977 on	\$ 30.00	BP95	Servo Kit, all XJ's 1969 on	\$ 35.00
BP38	Front Caliper Kit, Mk 9	\$135.85	BRAKE HOSES . All brake hoses are manufactured by Girling. Prices below are for each		
BP36	Front Caliper Kit 3.4 Mk 1, Mk 2, early 3.8 Mk 10	\$ 69.55	BH1	Brake Hose, Mk 5 (each) (2 req for front, 1 req for rear)	\$ 30.90
BP40	Front Caliper Kit, later 3.8 Mk 10	\$110.00	BH2	Front Left Hose	\$ 27.80
BP68	Front Caliper Kit, 4.2 Mk 10	\$100.00	BH4	Front Right Hose, Mk 7 and 8 with drum brakes	\$ 47.98
BP48	Front Caliper Kit, 3.4S, 3.8S, 420G	\$ 95.00	BH3	Front Hose, 420G, Mk 10	\$ 28.90
BP54	Front Caliper Kit 420, XJ6, and XJ12 up to 9/73	\$ 38.50	BH17	Front Hose, 420	\$ 32.00
BP50	Front Caliper Kit XJ6 and XJ12 10/73 on, XJS	\$ 50.00	BH8	Front Hose, 3.4 and 3.8 Mk 2, 3.8S, 3.4 Mk 1	\$ 42.70
BP39	Rear Caliper Kit, Mk 9	\$110.35	BH5	Rear Hose, Mk 7, Mk 8	\$ 30.00
BP37	Rear Caliper Kit, early 3.8 Mk 10	\$ 76.00	BH7	Rear Hose, 3.4 Mk 1, 3.4 and 3.8 Mk 2	\$ 54.00
BP41	Rear Caliper Kit, late 3.8 Mk 10	\$ 69.55	BH9	Rear Hose, 3.4 Mk 1, 3.4 and 3.8 Mk 2	\$ 54.00
BP49	Rear Caliper Kit 3.4S, 3.8S, 420G, 4.2 Mk 10	\$100.00	BH2	Front Hose, XJ6, XJ12, up to 9/73	\$ 27.80
BP43	Rear Caliper Kit, 3.4 Mk 1, Mk 2	\$ 55.00	BH13	Front Hose, XJ6, XJ12, 10/73 on XJS up to 1977	\$ 33.00
BP55	Rear Caliper Kit, all XJ's to 1977	\$ 80.44	BH15	Front Hose, XJS, 1977 on	\$ 48.00
BP96	Rear Caliper Kit, all XJ's 1977 on	\$ 32.00	BH12	Rear Hose, XJ6, XJ12, up to 9/73	\$ 23.00
CLUTCH REBUILD KITS			BH14	Rear Hose, XJ6, XJ12, 10/73 on	\$ 46.00
BP15	Master Cylinder Kit, Mk 7, Mk 8, Mk 9	\$ 30.00	BH16	Rear Hose, XJS	\$ 28.00
BP42	Master Cylinder Kit, 3.4S, 3.8S	\$ 10.00	BH18	Rear Hose, 420	\$ 30.00
BP44	Master Cylinder Kit Mk 1, Mk 2, 3.8 Mk 10, 420	\$ 5.00	BH20	Front Hose, 2.4 Mk 1	\$ 22.50
BP58	Master Cylinder Kit, 420G	\$ 40.65	BH21	Rear Hose, 2.4 Mk 1	\$ 20.00
BP61	Master Cylinder Kit 4.2 Mk 10, XJ6 to 5/73	\$ 5.00	BRAKE PIPES. These are the metal brake lines which connect the two halves of the caliper assemblies.		
BP45	Slave Cylinder Kit Mk 1, Mk 2, Mk 10, 420, 420G, 3.4S, 3.8S, XJ6 to 5/73	\$ 4.75	BP190	Front, Passenger Side	\$ 16.60
BP64	Slave Cylinder Kit, Mk 7, Mk 8, Mk 9	\$ 11.25	BP191	Front, Driver's Side	\$ 16.60
SERVO REBUILD KITS			BP192	Rear, Passenger Side	\$ 16.60
BP74	Servo Kit, Major, Repairs the slave cylinder on the booster. Mk 9, 3.4 Mk 1, Mk 2, 3.4S, 3.8S	\$ 24.60	BP193	Rear, Driver's Side. Fits MK II with disc brakes and 3.4,3.8 "S"	\$ 16.60
BP76	Servo Kit, Air Control Valve, Repairs the booster's control valve. Mk 9, 3.4 Mk 1, Mk 2, 3.4S, 3.8S	\$133.00	BP194	Rear Caliper Brake Pipe (each) (2 req) XJ6, XJ12, XJS	\$ 12.00
			CLUTCH HOSE		
			CH1	Clutch Hose, Mk 7, Mk 8, Mk 9	\$ 28.59
			MISCELLANEOUS BRAKE PARTS		
			BP119	Reservoir, Brake & Clutch fluid, single outlet (each) (2 req)	\$ 55.00
			BP151	Bleeder Screw	\$ 4.60
			BP152	Male Brake Line End—Mk 5, Mk 7, Mk 8	\$ 4.75
			BP153	Male Brake Line Fitting 3/8-24	\$ 1.50

BP160	Anti-squeal Pads (sheet of 4) These peel and stick to the back side of the disc brake pads	\$ 2.75
BP161	Front Brake Pad Shim Kit, XJ6 Series I	\$ 7.75
BP162	Front Caliper Hardware Kit, XJ6 Series I	\$ 4.75
BP164	Red Rubber Grease (2 oz tube) Used on wheel cylinder & caliper dust boots	\$ 6.00
BP165	Blue Mechanical Brake Grease (1oz tube) Used on linkages, etc.	\$ 5.00
H87	Screw, Secures Brake Drum to Hub Mk 5, Mk 7, Mk 8 (4 required)	\$ 1.65
REB8	Roller Bearing, Brake Pedal Pivot Fits Mark 5, 7, 8 and 9	\$ 17.65

SILICONE BRAKE FLUID

BF	Silicone Brake Fluid (quart)	\$ 17.65
----	------------------------------	----------

ENGINE PARTS

PISTON SETS. These pistons are supplied with rings, wrist pins and circlips.

MP28	3 1/2 Liter, 8 to 1 Compression. Available in standard, .020, .030, .040 oversizes (set of 6)	\$446.25
MP29	3.8 Liter, 8 to 1 Compression. Available in standard, .020, .030, .040 oversizes. (set of 6)	\$498.75
MP30	3.8 Liter, 9 to 1 Compression. Available in standard, .020, .030, .040, .060 oversizes. (set of 6)	\$498.75
MP21	4.2 Liter, 8 to 1 Compression. Available in standard, .020, .030, .040 oversizes. (set of 6)	\$472.50
MP21A	4.2 Liter, 9 to 1 Compression. Available in standard, .020, .030, .040, .060 oversizes. (set of 6)	\$472.50
MP95	5.3 Litre, 7.8 to 1 Compression (each)	\$ 90.95
MP95A	5.3 Litre, 9 to 1 Compression (each)	\$106.50
MP96	Piston and Liner Assembly (each) 5.3 litre, 7.8 to 1 compression	\$243.80
MP96A	Piston and Liner Assembly (each) 5.3 litre, 9 to 1 compression	\$243.80

PISTON RINGS

MP54	Piston Rings, 2.4 and 3.4 Litre. Available in standard, .020, .030, .040 oversizes. (set of 6)	\$106.50
MP56	Piston Rings, 3.8 Litre. Available in standard, .020, .030, .040 oversizes. (set of 6)	\$106.50
MP58	Piston Rings, 4.2 Litre. Available in standard, .020, .030, .040 oversizes. (set of 6)	\$ 80.25
MP59	Piston Rings, 5.3 Litre. (each set) Available in standard size only (3 sets required)	\$ 96.00

BEARINGS

PG1	Plastigauge. Measures clearances from .001" to .003"	\$ 3.25
MP1	Cam Bearings (set)	\$ 65.85
MP8	Main Bearing Set, standard	\$131.85
MP8A	Main Bearing Set, undersized. Available in .010, .020, .030 and .040. Fits 2.4, 3.4 and 3.8 motors	\$147.10

C4283	Crankshaft Oil Galley Plug (each) (6 required)	\$ 1.65
C28082	Main Bearing Cap Lock Washers (14 required)	\$ 1.00
MP11	Main Bearing Set, standard	\$106.50
MP11A	Main Bearing Set, undersized. Available in .010, .020 and .040. Fits all 4.2 motors	\$133.00
C23761	Crankshaft Oil Galley Plug (each) (6 required)	\$ 2.75
MP10	Rod Bearing Set, standard	\$ 79.45
MP10A	Rod Bearing Set, undersized. Available in .010, .020, .030 and .040. All 2.4, 3.4, 3.8 and 4.2 up to eng# BL51501	\$ 79.45
MP19	Rod Bearing Set, standard	\$ 60.00
MP19A	Rod Bearing Set, undersized. Available in .010, .020, .030 and .040. All 4.2 from eng# BL51502	\$ 75.00
MP2	Thrust Washers (set of 2) Fits 2.4, 3.4 and 3.8 with low compression	\$ 15.60
MP2A	Thrust Washers, oversized .005 (set of 2)	\$ 15.60
MP31	Thrust Washers (set) Fits 3.4 and 3.8 with 9:1 compression All 4.2	\$ 5.25
MP32	Wrist Pin Bushings (set of 6)	\$ 36.90

12 CYLINDER

MP92	Main Bearings (set) standard, .010, .020, .030. Specify Size	\$117.15
MP90	Rod Bearings (set) standard, .010, .020, .030. Specify Size	\$106.50
MP94	Standard Thrust Washers (set)	\$ 10.25

GASKET SETS

INDIVIDUAL GASKETS

JG1	Head Gasket Set Mk 7, Mk 8, Mk 9, 3.4 Mk 1, 3.4 Mk 2	\$ 90.95	ENGINE - 6 CYLINDER		
			OF14	Oil Filter Body Gasket, Mk 7, Mk 8	\$ 1.65
JG3	Head Gasket Set, Mk 9, 3.8 Mk 2	\$111.85	GA1	Cam Cover Oil Filler Gasket (all models)	\$ 3.10
JG5	Head Gasket Set, 3.8 Mk 10	\$149.00	GA4	Exhaust Manifold (to head) Gasket (each)	\$ 4.25
JG6	Head Gasket Set 4.2 Mk 10, 420 and 420G 1966-68	\$154.50	GA32	Intake Manifold Gasket (2 carb)	\$ 9.25
			GA31	Intake Manifold Gasket (3 carb)	\$ 9.25
JG7	Head Gasket Set, all 2.4 liter	\$110.00	GA54	Distributor Gasket	\$ 1.00
JG10	Head Gasket Set, 420, 420G, XJ6, 68-73	\$120.00	GA45	Water Pump Gasket, all 6 cylinders	\$ 1.50
JG12	Head Gasket Set, XJ6 74-78	\$120.00	GA56	Cover Vent Gasket	\$ 1.65
JG13	Head Gasket Set, XJ6 79 on	\$105.00	GA57	Timing Cover Housing Gasket	\$ 6.75
JG15	Head Gasket Set, V-12	\$133.00	GA59	Oil Screen Plate Gasket	\$ 2.75
JG2	Conversion Set All 2.4 motors to eng # BJ2263 All 3.4 motors to eng# KJ2790 except 3.4S All 3.8 motors to eng # LC8067 Except 3.8 Mk 10 and 3.8S	\$ 64.20	GA60	Oil Pump Body O-ring (each) (2 required)	\$ 1.65
			GA50	Otter Switch Gasket	\$ 1.65
			MP23	Intake Valve Guide Seal (each) (6 required) Mk 10, XJ6	\$ 2.50
JG21	Conversion Set All 2.4 motors from eng # BJ2264 All 3.4 motors from eng# KJ2791 3.4S All 3.8 motors from eng#LC8068 3.8 Mk 10, 3.8S	\$ 53.50	“O” RINGS		
			R43	Cam Cover O Ring (each) (2 req) All 6 cylinder with DOHC	\$ 1.15
			OF13	Oil Cannister Sealing Ring	\$ 2.75
JG22	Conversion Set All 4.2 motors to early 1968	\$ 58.85	ENGINE SEALING WASHERS		
			MP5	Copper Cam Cover Washer (each) (23 req) Fits 3.8, 4.2 motors	\$.65
JG23	Conversion Set All 4.2 motors 1968 on	\$ 26.75	MP5A	Sealing Washers for Cylinder Head Stud (each) (6 per car)	\$ 1.20
			MP5B	Copper Washer used on Oil Galley Plugs and under Water Drain Petcock (each) (7 req)	\$ 2.50
JG25	Conversion Set, 5.3 liter	\$ 35.75			
JG8	Oil Pan Gasket Set, 3.4 (replacement)	\$ 23.55	MP5C	Copper Washer used for Large Oil Galley Plug on rear of Block (all 6 cyl engines)	\$ 2.50
JG30	Oil Pan Gasket Set, all 6 cylinder	\$ 12.85			

CAM COVER GASKET SETS

VALVES, GUIDES AND SPRINGS. We stock only silicone bronze guides in the proper oversize, so there is no reaming required. These are the finest guides available and will last considerably longer than the cast iron as originally supplied.

6 CYLINDER

JG40	Mk 1, Mk 7, Mk 8 Mk 9 with mechanical tach drive	\$ 17.65			
JG41	Mk 9 with electrical tach drive—Mk 10, Mk 2, 3.4S, 3.8S, Series I XJ6, early Series II XJ6	\$ 17.65	MP12	Intake Valve Guide (each) Fits all up to 1968 eng# 7D 55849	\$ 6.25
			MP85	Intake Valve Guide (each) Fits all 4.2 from 1968 eng# 7D55850	\$ 6.25
JG43	Later Series II XJ6, Series III XJ6	\$ 16.50	MP13	Exhaust Valve Guide (each) Fits all 6 cylinder	\$ 6.25
JG42	All V-12 Motors	\$ 17.65	MP14	Intake Valve (each) Fits Mk 7, Mk 1	\$ 23.55
			MP33	Intake Valve (each) Fits Mk 8, Mk 9, Mk 10, Mk 2 And all 4.2 motors with carburetors	\$ 16.00
			EAC1395	Intake Valve, XJ6 Series III (each)	\$ 20.00

MP16 Exhaust Valve (1-7/16" head) (each) \$ 23.55
Fits Mk 7, Mk 1

TIMING COMPONENTS

6 CYLINDER DOHC MOTORS

MP17 Exhaust Valve (1-5/8" head)(each)Fits Mk8 \$ 21.40
Mk 9, Mk 10, Mk 2 and all 4.2 motors

MP3L Lower Timing Chain \$ 24.60
MP3U Upper Timing Chain \$ 29.95

MP18 Iskenderian Racing Valve Spring Set \$106.50

3.8 & 4.2 LITER ONLY

MP34 Valve Stem Collar Set \$ 13.35
12 pieces/set, 2 sets required

MP100 Upper Cam Sprocket \$ 58.85
MP101 Cam Chain Adjuster Sprocket \$117.15
MP102 Cam Chain Adjuster Plate \$ 37.45

12 CYLINDER

MP87 Intake Valve Guide (each) \$ 6.25

MP103 Double Sprocket—Connects the upper and lower chains \$169.75

MP86 Exhaust Valve Guide (each) \$ 6.25

MP104 Crank Sprocket \$ 74.90

MP88 Intake Valve (12 required) \$ 16.00

MP109 Intermediate Damper Plate—for upper timing chain \$ 31.05

MP89 Exhaust Valve (12 required) \$ 19.20

MP110 Lower Chain Damper Plate, Right \$ 15.15

VALVE ADJUSTING SHIMS

MP111 Lower Chain Damper Plate, Left \$ 16.00

MP70A Valve Adjusting Shim .085 Thick \$ 3.25

MP112 Upper Chain Damper Plate, Right \$ 12.85

MP70B Valve Adjusting Shim .086 Thick \$ 3.25

MP113 Upper Chain Damper Plate, Left \$ 12.85

MP70C Valve Adjusting Shim .087 Thick \$ 3.25

MP114 Tensioner, Lower Chain \$ 37.45

MP70D Valve Adjusting Shim .088 Thick \$ 3.25

MP122 Crankshaft Distance Piece. Spacer on end of crankshaft that the timing cover seal rides against. Updated version with internal "O Ring" Seal \$112.99

MP70E Valve Adjusting Shim .089 Thick \$ 3.25

MP122A Internal "O Ring" Seal for Crankshaft Distance Piece \$ 2.55

MP70F Valve Adjusting Shim .090 Thick \$ 3.25

12 CYLINDER

MP70G Valve Adjusting Shim .091 Thick \$ 3.25

MP84 Timing Chain \$ 42.80

MP70H Valve Adjusting Shim .092 Thick \$ 3.25

MP105 Camshaft Sprocket \$ 69.55

MP70I Valve Adjusting Shim .093 Thick \$ 3.25

MP106 Jackshaft Sprocket \$ 58.85

MP70J Valve Adjusting Shim .094 Thick \$ 3.25

MP107 Crank Sprocket \$106.50

MP70K Valve Adjusting Shim .095 Thick \$ 3.25

MP115 Lower Chain Damper Plate \$ 16.00

MP70L Valve Adjusting Shim .096 Thick \$ 3.25

MP116 Upper Chain Damper Plate, Left \$ 10.25

MP70M Valve Adjusting Shim .097 Thick \$ 3.25

MP117 Upper Chain Damper Plate, Right \$ 21.40

MP70N Valve Adjusting Shim .098 Thick \$ 3.25

MP118 Chain Tensioner \$ 58.85

MP70O Valve Adjusting Shim .099 Thick \$ 3.25

MP46 Timing Chain Inspection Plug \$ 5.25

MP70P Valve Adjusting Shim .100 Thick \$ 3.25

TAPPET HOLDOWN KITS

MP70Q Valve Adjusting Shim .101 Thick \$ 3.25

MP150 Tappet Holdown Kit \$ 58.85
This kit anchors the tappet guide sleeves in the head and prevents the sleeves from lifting up and making contact with the camshaft. One kit does on camshaft. Fits all DOHC 6 cylinder motors

MP70R Valve Adjusting Shim .102 Thick \$ 3.25

MP70S Valve Adjusting Shim .103 Thick \$ 3.25

MP70T Valve Adjusting Shim .104 Thick \$ 3.25

MP70U Valve Adjusting Shim .105 Thick \$ 3.25

CAMSHAFT TIMING TOOLS

MP70V Valve Adjusting Shim .106 Thick \$ 3.25

MP99 Camshaft Alignment Tool, all DOHC 6 & 12 \$ 26.75

MP70W Valve Adjusting Shim .107 Thick \$ 3.25

MP99A Timing Chain Adjusting Tool, DOHC 6 \$ 44.50

MP70X Valve Adjusting Shim .108 Thick \$ 3.25

MP70Y Valve Adjusting Shim .109 Thick \$ 3.25

MP70Z Valve Adjusting Shim .110 Thick \$ 3.25

HARMONIC BALANCER

Our rebounded dampers are sold on an **exchange** basis only and can be shipped immediately from our stock. If you desire to have yours rebounded, turnaround time is approximately 6 weeks. All pieces are stripped, blasted and rebounded with a modern blend of rubber (as used in the aircraft industry) using modern techniques of metal bonding. They are guaranteed against separation. It is necessary to rebalance the engine. The timing marks on the damper should be set up with a dial indicator and degree wheel if the engine does not have the timing mark arrow on the flywheel.

HBAL1	Rebonded Harmonic Balancer # 51/77 with 1/2" thick metal plate	\$143.75
HBAL2	Rebonded Harmonic Balancer # 51/211 with 3/8" thick metal plate	\$143.75
HBAL3	Rebonded Harmonic Balancer Fits all 4.2 liter engines	\$143.75

MISCELLANEOUS ENGINE PARTS

AB1	Cylinder Head Vent Breather Pipe Aluminum coated and reinforced flexible corrugated tubing Mk 7, Mk 8, Mk 9, Mk 1, Mk 2	\$ 24.80
MP60	Connecting Rod Bolt and Nut Set, 6 cyl Set of 12 for one motor	\$ 83.45
MP60C	Connecting Rod Bolt and Nut Set, 6 cyl Competition Quality (set of 12)	\$ 90.95
MP126	Studs, Cylinder Head, 6 cyl OEM Quality (each) (14 req)	\$ 14.50
MP126C	Studs, Cylinder Head, 6 cyl Competition Quality (each) (14 req)	\$ 18.15
MP121	Studs to attach Exhaust Pipes to Manifold (8 req) Mk 7, Mk 8, Mk 9	\$ 1.85

CLUTCH PARTS

2.4 with 9" Clutch

MP20D	Clutch Disc	\$ 75.00
MP26D	Clutch Pressure Plate	\$125.00
MP27	Throw Out Bearing	\$ 38.65

3.4 and 3.8 with 10" Clutch

MP20	Clutch Disc, 3.4 Mk 1, 3.4 Mk2, 3.8 Mk 10, Mk 7, Mk 8, Mk 9, 3.4S	\$ 90.95
MP26	Clutch Pressure Plate, 3.4 Mk 1, 3.4 Mk 2, 3.8 Mk 10, Mk 7, Mk 8, Mk 9, 3.4S	\$238.50

MP27	Throw Out Bearing, 3.4 Mk 1, 3.4 Mk 2, 3.8 Mk 10, Mk 7, Mk 8, Mk 9, 3.4S	\$ 68.00
------	--	----------

3.8 and 4.2 with 9" Clutch

MP20A	Clutch Disc, 3.8 Mk 2, 3.5S, all 4.2	\$ 96.00
MP26A	Clutch Pressure Plate, 3.8 Mk 2, 3.8S, all 4.2	\$159.75
MP27A	Throw Out Bearing, 3.8 Mk 2, 3.8S, all 4.2	\$ 35.30

5.3 with 10" Clutch

MP22A	Clutch Disc	\$243.80
MP22	Clutch Pressure Plate	\$138.45
MP22B	Throw Out Bearing	\$ 37.45

Miscellaneous

MP24	Manual Transmission Pilot Bushing	\$ 8.25
MP25	Clutch Alignment Tool	\$ 8.20
MP35	Flywheel Dowl Pin (each) 5/16" diameter (3 required)	\$ 1.00

Ring Gears

RG1	Fits 3 1/2 Liter (132 teeth)	\$133.15
RG2	Fits 3.8 Litre (104 teeth)	\$ 87.20
RG3	Fits 4.2 Litre (133 teeth)	\$106.50

TRANSMISSION PARTS

AUTOMATIC TRANSMISSION FILTER KITS

ATF1	Filter Kit, Borg Warner T35 - 1962-1966 Mk 2, Mk 10, 3.4S, 3.8S, 420, 420G	\$ 16.00
ATF2	Filter Kit, Borg Warner T35—Filter has a curved extension 1967-1971 420G, 340, 380, some Series I XJ6	\$ 11.00
ATF3	Filter Kit, Borg Warner T400 1978 on XJS	\$ 11.00
ATF4	Filter Kit, Borg Warner T65, T66 Series II & III J6, XJ12 with aluminum case	\$ 11.00
ATF5	Filter Kit, Borg Warner T8, T12 with cast iron case Some Series I XJ6, XJS to 1978	\$ 11.00

STD TRANSMISSION GASKETS

SS40	Seal & Gasket Kit, Manual trans not OD. Contains front gasket, top gasket, rear gasket, tailpiece gasket, countershaft o-ring, reverse shaft seal, fiber shaft plug, 3 shift rail felt seals, front seal & rear seal	\$ 44.10
GA80	Front Cover Gasket	\$ 4.75
GA81	Top Cover Gasket (each) (2 req on OD)	\$ 4.75
GA82	Rear Cover Gasket	\$ 4.75

OVERDRIVE GASKETS

Mk 7, Mk 8, Mk 9

GA83 Adaptor Plate to Casing Gasket \$ 4.00

GA84 Gasket behind solenoid mounting plate \$ 2.50

GA85 Solenoid Housing Cover Plate Gasket \$ 2.50

Miscellaneous

C1838 Front Input Shaft Roller Bearing \$ 42.80

C1845 Rear Transmission Roller Bearing \$ 85.50

CNB1 Countershaft Needle Bearings (58/pkg) \$ 55.65

CNB2 Needle Bearings, 2nd & 3rd gear (82/pkg) \$ 88.50

REB8 Roller Bearings, Inside of Constant Pinion Shaft \$ 17.65

C294 Trans, Rear Extension Bearing "SH" type \$ 40.00

GA86 Tailpiece Gasket, Manual Transmission \$ 4.25

SS36 Shift Rail Felt Seals \$ 1.25

SS37 Countershaft Fiber Plug \$ 1.50

SS38 Reverse Shaft Seal \$ 4.75

SS39 Countershaft "O Ring" \$ 2.30

C1861 Thrust Washer \$ 5.25

C1862 Thrust Washer \$ 5.25

JC9 Original Style Shift Knob-black know with shift pattern—Mk 7, Mk 8, Mk 9 \$ 17.10

JC9A Jam Nut, Stainless \$ 1.50
Used for positioning shift knob

FUEL SYSTEM

AIR FILTERS

AF10 Mk 10, 420, 420G \$ 16.30

AF11 3.4S, 3.8S \$ 5.50

AF13 XJ6 with carburetors \$ 13.85

AF15 XJ6 with fuel injection \$ 14.40

AF16 XJ12, 73-74 \$ 12.50

AF17 XJ12, XJS, 75-77 with carburetors \$ 20.80

AF18 XJ12, XJS, 78 on (each) \$ 18.47
With fuel injection (2 required)

AF20 XJ6, XJ40, 1988-94 \$ 12.00

BANJO BOLTS

AUC2698 Banjo Bolt for Carburetor & Fuel Pump \$ 8.25

CARB REBUILDING KITS

These kits contain all gaskets and seals with a float needle & seat, the main jet, And metering needle.

Solex Carbs

SU5 Carburetor Rebuild Kit, 32PBI type. Fits all 2.4 motors \$ 26.00

SU Carbs

SU1 Carburetor Rebuild Kit, HD6 type. Fits 3.4 and 3.8 Mk 2 \$ 70.30

SU2 Carburetor Rebuild Kit, H6 type. Fits Mk 7, Mk 8 \$ 85.69

SU3 Carburetor Rebuild Kit, HD8 type. Fits Mk 10, 420 (each) (3 kits required) \$ 74.90

SU4 Carburetor Rebuild Kit, HD6 type. Fits Mk 8, Mk 9, 3.4 and 3.8 Mk 1 66-68 3.8S \$ 72.65

SU25 Carburetor Float (brass) \$ 38.25

Zenith Stromberg Carbs

SU8 Carburetor Rebuild Kit, XJ6 (each) (2 required) \$ 38.80

SU9 Carburetor Rebuild Kit, XJ12 (each) (4 required) \$ 38.80

SU30 Anti Run-on Diaphragm, XJ12 (each) (4 required) \$ 11.00

Carb Gaskets and Spacers

GA10 Carb to Air Filter Gaskets (each).Fits all models with 2" carbs \$ 1.50

GA10A Carb to Manifold Gaskets (each) Fits all models with 2" carbs \$ 1.00

GA10B Carburetor Insulating Blocks (each) Fits all models with 2" carbs \$ 7.75

GA98 Gasket, Square Base SU Fuel Pump \$ 3.25

Zenith Stromberg Carbs

GA13 Carb to Manifold Gaskets (each) \$ 1.10

GA17 Carb to Air Filter Gaskets (each) \$ 1.10

GA8 Carburetor Insulating Blocks (each) \$ 4.00

FUEL PUMPS

FP1 SU Butec Positive Ground Fuel Pump. Mk 5, Mk 7, Mk 8, Mk 9, Mk 10, 420, 420G, Mk 1, Mk 2, 3.4S, 3.8S, all up to 1964 \$149.00

FP1A Square Base Fuel Pump, Positive Ground, SU \$349.95

FP1K Adapter Kit for FP1. Contains an adapter bracket, banjo bolts and fittings, washers, and all other pieces required to convert From the original square-based pump. Mk 7, 8 & 9 require 2 kit. Mk 5 model uses 1 kit. \$ 64.25

FP2 Original SU Fuel Pump. Negative Ground \$117.15
Mk 2, 3.4S, 3.8S, all XJ6 with carbs

FP6 Original SU Fuel Pump (each) (2 req) all XJ12 with carbs \$215.25

FP10 Fuel Pump Point Set. Fits original SU pumps (FP2, FP3) \$ 12.85

FP11 Fuel Pump Rebuild Kit. Contains new diaphragms and gaskets (2-3/8" shaft length) Mk 5, Mk 7, Mk 8, Mk 9 \$ 25.70

FP11A Fuel Pump Kit—Sq Base—SU Long Shaft \$ 25.70

GA98 Gasket, Square Base SU Fuel Pump \$ 3.25

FUEL FILTERS

FF1 Fuel Filter. Used on the glass float bowl filter body. Fits Mk 8, Mk 9 \$ 5.35

FF2 Universal Inline Fuel Filter \$ 6.50

FF3 Fuel Filter. Used in the metal cannister type filter body. Usually installed in the trunk. XJ6 and XJ12 up to 1974 \$ 10.20

FF5 Fuel Filter, XJ6 1975-77 \$ 11.95

FF7 Fuel Filter, XJ12 and XJS 1975-79 \$ 14.70

FF8 Fuel Filter, XJ6 1978-79 \$ 10.90

FF9 Fuel Filter, XJ6 and XJS 1980 on \$ 26.25
Note: FF8 and FF9 were sometimes interchanged at the factory. FF8 has a body diameter of 2-1/8" while FF9 has a body diameter of 2-7/8".

FUEL TANK SENDING UNITS

GA6 Fuel Tank Sending Unit Gasket \$ 2.25
 Fits Mk 7, Mk 8, Mk 9

Sending units for the Mk 7, 8, 9 and 10 aren't available. If your old one is complete, we can rebuild it. Call for price and availability.

CARB ADJUSTING TOOLS

SU10 Zenith Stromberg Adjustment Tool. Inserts \$ 16.30
 from the top of the damper housing.

MISCELLANEOUS

FPP Pipe, Fuel Tank to Fuel Pump. XJ6, XJ12 \$ 18.50

OF9 Flexible Fuel Line (with standard female ends). Mk 7, Mk 8, Mk 9 \$ 58.10

OF9A Flexible Fuel Line (with banjo fitting) \$ 23.75
 Mk 9

SU20 Starting Carburetor Solenoid \$101.50

E61 Carburetor Solenoid Switch (starting carb thermostat) Mk 7, Mk 8, Mk 9, Mk 10, Mk 1, Mk 2, 3.4S, 3.8S \$ 80.25

GA50 Otter Switch Gasket \$ 1.65

OIL SYSTEM

OIL FILTERS

OF1A Oil Filter Cannister Adapter. Converts the longer style \$ 40.10
 early

Cannister to be able to use the later short felt oil filter. No outward appearance change.
 Early Mk 7 (Engine# W1001-W4382)

OF2 Felt Oil Filter, Mk 7, Mk 8, Mk 9 \$ 24.10

OF3 Felt Oil Filter, Mk 1, Mk 2, Mk 10, 3.4S, 3.8S, 420, 420G \$ 17.80

OF6 XJ6, 68-74 \$ 8.00

OF5 XJ12, 72-75 \$ 6.00

OF7 XJ12 and XJS, 1975 on XJ6, 75-78. This filter is 5-1/2" long \$ 12.00

OF8 XJ6, 78 on with fuel injection. This filter is 4-3/4" long \$ 14.00

OIL FILTER CONVERSION KIT

Converts your old style cannister filter to a modern easy to change spin on oil filter. Comes complete with instructions and all necessary parts including filter. Converts back easily with no appearance change.

OF16 Oil Filter Conversion Kit. Fits Mk 1 2.4 & 3.4 \$ 96.00
 Fits Mk 2 3.4 & 3.8

OF18 Oil Filter Conversion Kit. Fits Mk 7, Mk 8, Mk 9 \$127.75
Note: It is necessary for you to send in your old Oil Filter Body Housing for modification.

OF19 Oil Filter Conversion Kit. Fits "S" types, 420, 420G \$ 96.00
 Fits Mk 10 3.8 & 4.2

OF21 Oil Filter Conversion Kit. Fits XJ6 Ser I 4.2 \$115.00

OIL PUMPS

OP1 Oil Pump, all 4.2 liter \$117.15

OP2 Oil Pump, all 3.8 liter \$117.15

MISCELLANEOUS

SS2 Oil Filter Body Seal. Fits inside cannister below filter \$ 1.60
 plate.
 MK 7, Mk 8, Mk 9

OPS2 Oil Pressure Sending Unit. Fits XJ6 up to 12/70 \$117.15
 Mk 2, 3.4S, 3.8S, Mk 10, 420, 420G

OPS5 Oil Pressure Gauge Transmitter. XJ6 & 12, 5/76 on \$ 55.10
 XJS, 2/76 on

OP6 External Oil Line Washers (package of 6) \$ 4.75

MP38 Oil Pan Drain Plug and Sealing Washer. Fits all sedans \$ 12.30

OH10 Oil Return Hose. From relief valve to the oil pan.. \$ 7.25
 Fits Mk 1, Mk 2, Mk 10, 3.4S, 3.8S, 420, 420G

OF10 Flexible Oil Line. All early sedans with mechanical gauge \$ 32.10

OF15	Banjo Bolt to attach Oil Pipe to Cylinder Head and Block	\$ 10.80	FBT33	Fan Belt, Grooved Style, 3.8 Mk 10	\$ 30.00
			125X1200	Fan Belt, 4.2 Mk 10, 420 & 420G	\$ 16.50
COOLING SYSTEM					
WATER PUMPS					
We are now able to offer rebuilt water pumps for your Jaguar. These are sold on an Exchange Basis Only . We have several on the shelf ready for shipment or we can have your specific core rebuilt. All of our pumps come with a one year warranty and are identified by the casting numbers on the pump housings.					
WP2	Mark 8, Early Mark 9, Casting# C7452	\$106.50	125X950	Power Steering/Water Pump Belt	\$ 13.00
WP3	Late Mk 9, Mk 2, 3.8 Mk 10 Casting# C14944	\$106.50	95X888	Air Pump Belt	\$ 8.50
			125X1000	Air Conditioner Belt	\$ 15.25
WP4	Mk 1and 2 with 2.4 litre Casting# C8635	\$100.00	XJ6 Series I (1969-73)		
WP5	Mk 5, Casting# C522	\$120.00	95X950	Alternator Belt, Butec Alternator	\$ 8.75
WP7	Mk 7, Casting# C4938	\$120.00	95X888	Alternator Belt, Lucas Alternator	\$ 8.50
WP20	XJ6 to 1972, Casting# P30961A	\$ 95.00	125X950	Power Steering/Water Pump Belt	\$ 13.00
WP21	XJ6 1972-74, Casting# P30961B	\$ 95.00	95X888	Air Pump Belt	\$ 8.50
WP22	XJ6 1974-76, Casting# P30961C	\$ 95.00	125X1000	Air Conditioner Belt	\$ 15.25
WP23	XJ6 1976-82, Casting# P30961D	\$ 95.00	XJ6 Series II (1974-78)		
WP24	XJ6 1982 on, Casting# P30961E	\$ 95.00	95X888	Alternator Belt	\$ 8.50
WP30	XJ12, Casting# P36297	\$100.00	125X1200	Power Steering/Water Pump Belt	\$ 16.50
WP35	XJS, Casting# EAC2109	\$100.00	95X888	Air Pump Belt	\$ 8.50
			125X1000	Air Conditioner Belt	\$ 15.25
BEARINGS AND SEALS					
SS1	Water Pump Shaft Seal, Mk 5, Mk 7	\$ 10.25	XJ12, XJS		
WPB1	Outer Pump Bearing, Mk 5, Mk 7	\$ 21.00	95X850	Alternator Belt	\$ 8.00
WPB2	Inner Pump Bearing, Mk 5, Mk 7	\$ 19.95	125X825	Fan Belt	\$ 11.80
			125X1075	Power Steering/Water Pump Belt	\$ 14.50
FAN CLUTCHES					
WPC1	Bolt-on Style, XJ6 up to 73	\$135.00	GFB270	Air Conditioner/Air Pump Belt	\$ 12.00
WPC2	Press-on Style, all Series II	\$100.00	MISCELLANEOUS		
EAC4381	Series III Bolt-on up to @ VIN# 354477	*****	MP36	Large Freeze Plug (7 req) Concave Style Mk 7, Mk 8, Mk 9, Mk 10, Mk 1, Mk 2	\$ 1.25
EAC4751	Series III Bolt-on from @ VIN# 354478 on	\$150.00	MP37	Small Freeze Plug (1 req) Concave Style Mk 7, Mk 8, Mk 9, Mk 10, Mk 1, Mk 2	\$ 1.25
FAN BELTS					
FBT1	Fan Belt, Mk 7 Fits 50-53 with 5 or 6 Bladed fans	\$ 23.20	G10	Radiator Cap, Mk 4, Mk 5, Mk 7, Mk 8, Mk 9, Mk 1 Mk 2, 3.4S, 3.8S	\$ 8.75
95X1050	Fan Belt, Mk 7. Fits 53 on with 8 bladed fans	\$ 10.00	G12	Radiator Cap, Mk 10, 420, XJ6, 1968-70	\$ 6.25
95X1050	Fan Belt, Mk 8 to eng# 8974	\$ 10.00	G14	Radiator Cap, 1970 on, all models	\$ 6.25
95X1025	Fan Belt, Mk 8 from eng# 8975	\$ 9.75	G9	Manifold Filler Cap, XK6 & XJ12	*****
125X1000	Fan Belt, Mk 9	\$ 15.25			

G11	Fitting for temp gauge bulb in intake manifold. Mk 5, Mk 7, Mk 8, Mk 9, Mk 1	\$ 8.75	Mark 2, 3.4, 3.8		
			ESS4	Exhaust Flange Gasket (each) (2 req)	\$ 3.75
TRM1	Summer Thermostat, all 3.4 motors	\$ 8.25	R40	Exhaust Mount (each) (4 req)	\$ 6.00
TRM2	Winter Thermostat, all 3.4 motors	\$ 8.25	3.4S, 3.8S, 420		
TRM3	Summer Thermostat, all 3.8 & 4.2 motors	\$ 9.25	ESS4	Exhaust Flange Gasket (each) (2 req)	\$ 3.75
TRM4	Thermostat, 88-C, XJ6, 1982-1/2 on	\$ 10.00	R41	Intermediate Pipe Mount (each) (2 req)	\$ 6.00

AIR CONDITIONING

MARK 10, 420G

ACD1	Air Conditioner Drier Fits XJ6 and XJ12, Series I and II	\$ 35.00	ESS4	Exhaust Flange Gasket (each) (2 req)	\$ 3.75
			R41	Intermediate Pipe Mount (each) (2 req)	\$ 6.00
ACD2	Air Conditioner Drier, XJS 76-78	*****			
ACD3	Air Conditioner Drier Fits XJS 78 on and XJ6 Series III	\$ 57.50			
ACP	Air Conditioner Compressor, Rebuilt Fits all XJ's with G.M. compressor's	\$185.00			

CABLES

TACHOMETER CABLES

EXHAUST SYSTEMS

MARK 5

ESS6	Exhaust Flange Gasket (each) (3 req)	\$ 8.20
R41	Exhaust Mount (each) (2 req)	\$ 6.00

MARK 7

ESS6	Exhaust Flange Gasket (each) (2 req)	\$ 8.20
ESS15	Headpipe to Muffler Gasket	\$ 7.50
R40	Exhaust Mount (each) (2 req)	\$ 6.00
R41	Exhaust Mount (each) (4 req)	\$ 6.00
R38	Tailpipe Mount	\$ 14.95

MARK 8

ESS6	Exhaust Flange Gasket (each) (2 req)	\$ 8.20
R41	Exhaust Mount (each) (3 req)	\$ 6.00
R38	Tailpipe Mount	\$ 14.95

MARK 9

ESS6	Exhaust Flange Gasket (each) (2 req)	\$ 8.20
R41	Exhaust Mount (each) (4 req)	\$ 6.00
R38	Tailpipe Mount	\$ 14.95

MARK 1, 2.4

ESS4	Exhaust Flange Gasket (each) (2 req)	\$ 3.75
R40	Exhaust Mount (each) (3 req)	\$ 6.00

MARK 1, 3.4

ESS4	Exhaust Flange Gasket (each) (2 req)	\$ 3.75
R40	Exhaust Mount (each) (3 req)	\$ 6.00

CABLE DRIVE GEARBOXES

MARK 2

The original tachometer gearbox drive used on the Mark 2 with the mechanical tachometers is no longer available. The following replacement gearbox requires a special cable which fits into the slotted drive end of the gearbox (as opposed to the square drive found on the original gearbox)

E11A	Mechanical Tachometer Gearbox (replacement)	*****
E11B	Tachometer Cable for E11A	*****
GB3	Speedometer Gearbox, Transmission End fits 3.4S and 3.8S with overdrive. All XJ6 and Series I & II XJ12. All XJS with standard transmissions and automatics up to 7/76	\$ 62.50
GB4	Speedometer Gearbox, Transmission End. Fits XJ12 Series III. XJS with automatic trans from 5/77 on	\$ 62.50
GB8	Speedometer Gearbox, Speedo End. Fits XJ6 to 9/72 And XJ12 to 8/73	\$ 55.00
GB9	Speedometer Gearbox, Speedo End. Fits XJ6 from 1/75 to 8/80. XJ12 from 9/73 on	\$ 55.00

SUSPENSION

BALL JOINTS

BJ1	Lower ball joint kit (does both sides) Contains 2 ballpins, 2 bronze cups and 2 castle nuts. Fits Mk 5, Mk 7, Mk 8, Mk 9	\$106.50
BJ1A	Lower ball joint upper spigot (each) (2 req)	\$ 8.75
BJ1B	Lower ball joint boot retainer (each) (2 req)	\$ 8.75

BJ1C	Lower ball joint capscrew locktab (each) Fits Mk 5, Mk 7, Mk 8, Mk 9 (4 req)	\$ 3.50	R122	Front Subframe Mount (each) (2 req) Mk 2, 3.4S, 3.8S, 420	\$ 24.95
			SP20L	Lower Control Arm Bushing (each) (4 req) Mk 1, Mk 2, Mk 10, 3.4S, 3.8S, 420, 420G, XJ6, XJ12, XJS	\$ 6.25
BJ6A	.003 Lower Ball Joint Shim	\$ 4.25			
BJ6B	.005 Lower Ball Joint Shim	\$ 4.25	SP20U	Upper Control Arm Bushing (each) (8 req) Mk 1, Mk 2, Mk 10, 3.4S, 3.8S, 420, 420G	\$ 7.25
BJ6C	.010 Lower Ball Joint Shim	\$ 4.25			
	Fits Mk 5, Mk 7, Mk 8, Mk 9		SP20	Control Arm Bushing Set (8 pieces) Mk 1, Mk 2, Mk 10, 3.4S, 3.8S, 420, 420G	\$ 55.65
BJ7	Ball Joint Gaiter Boot (each) Fits Mk 5, Mk 7, Mk 8, Mk 9	\$ 5.75			
			SP31	Upper Control Arm Bushing (each) (4 req) XJ6, XJ12, XJS	\$ 28.90
BJ2	Upper Ball Joints (pr) Fits Mk 1 and Mk 2 except some 2.4, Mk 5, Mk 7, Mk 8, Mk 9, Mk 10, 420, 420G, 3.4S, 3.8S, all XJ's	\$ 96.00	R18	Sway Bar "D" Mounting Rubber (each) (2 req) Fits Mk 1 & 2	\$ 7.45
			R127	Panhard Rod Bushing, Mk 2 (each) (4 req)	\$ 3.25
			R158	Sway Bar Bushings—XJ6, XJ12, XJS	\$ 7.45
BJ3	Upper Ball Joints (pr) 2.4 Mk 1 to Chassis# 912621 2.4 Mk 2 to Chassis# 943266	\$ 70.00	Mk 5, Mk 7, Mk 8, Mk 9		
			R16	Sway Bar Link Eye Bushing (each) (4 req)	\$ 2.35
BJ4	Lower Ball Joint Repair Kit (2 req) Fits Mk 1, Mk 2, Mk 10, 3.4S, 3.8S, 420, 420G all XJ's.	\$ 48.15	R17	Sway Bar "D" Rubber Bushing (each) (2 req)	\$ 3.25
			R127	Sway Bar Link Upper Mounting Bush (each) (4 req)	\$ 3.25
	TIE RODS AND ENDS		R15	Anti-Sway Bar Block and Bushing Set. Contains all of the above bushings	\$ 25.70
SP1	Track Rod End Pin and Bushing, Mk 5, Mk 1, Mk 2, Mk 10, 420, 420G, 3.4S, 3.8S	\$ 21.40			
				REAR SUSPENSION MOUNTS	
SP1A	Machining and Installation of bushings in your track rod ends. You must send in your track rod ends. Mk 5, Mk 1, Mk 2, Mk 10, 420, 420G, 3.4S, 3.8S	\$ 37.45		These mounts fit all models with I.R.S. Mk 10, 3.4S, 3.8S, 420, 420G, XJ6, XJ12, XJS	
			SP21	Radius Arm Mounts, Forward (each)	\$ 33.70
SP2	Tie Rods Ends (set of 2) Mk 5	\$ 57.80	SP22	Radius Arm Mounts, Rear (each)	\$ 16.00
SP3	Steering Side Rods (pair) Mk 1, Mk 2	\$ 75.00	SP23	Subcage Mounts, Rear (each) (4 req). Metalistic "V" Blocks that mount the rear suspension in chassis	\$ 37.45
SP11	Tie Rod Assemblies (pair) Mk 10	\$150.00			
SP13	Tie Rod Assemblies (pr) Mk 7, Mk 8, Mk 9	\$176.00		SUSPENSION SPRINGS	
SP18	Steering Rod Ends (pair for 1 side rod) Mk 10, 420G	\$ 30.00	HS5	Rear Leaf Springs—Mk 5, Mk 7, Mk 8, Mk 9	\$295.00
			HS6	Rear Leaf Springs—Mk 1, Mk 2	\$295.00
SP19	Tie Rod Ends (set of 2) XJ12, XJS, XJ6 up to VIN# 345390 (mid 82). These ends have a 5/8" I.D. thread (16mm)	\$ 53.50		You must provide the center mount. Springs come with rear mounts and bushings.	
			R156	Rear Spring Mounting Pad, Mk 1 & 2. Attaches to the front of rear spring	\$ 10.80
JLM9660	Tie Rod End (each) (2 req) XJ6 Series III from VIN# 345391 (mid 82). These ends have a 9/16" I.D. thread (14mm)	\$ 45.00	CS10	Front Coil Spring, Mk 2	\$100.00
			CS3	Rear Coil Spring (each) (4 req) XJ6, XJ12, XJS	\$ 75.00
	SUSPENSION BUSHINGS			UNIVERSAL JOINTS	
SP7L	Lower Control Arm Bushing (each) (8 req)	\$ 11.43	SCJ1	Steering Column U-Joint (each) Mk 1, Mk 2 (2 req) Mk 10, 420, 420G, 3.4S, 3.8S, XJ6, XJ12, XJS	\$ 37.45
SP7U	Upper Control Arm Bushing (each) (8 req)	\$ 9.20			
SP7	Control Arm Bushing Set (16 pieces) Mk 5, Mk 7, Mk 8, Mk 9	\$136.00	SCJ2	Steering Column Metalastic Coupling (each) (2 req) Mk 1, Mk 2, Mk 9	\$ 42.80

SCJ3	Drive Shaft U-Joint. Measures 3" from cap to cap. Mk 5, Mk 7, Mk 8, Mk 9, Mk 1, early Mk 2	\$ 29.95	Rebound Rubbers	BS1	Front Rebound Rubber (each) Mk 5, Mk 7, Mk 8, Mk 9	\$ 16.00
SCJ4	Drive Shaft U-Joint. Measures 3 1/4" from cap to cap. Late Mk 2, Mk 10, 420, 420G, 3.4S, 3.8S, XJ6, XJ12, XJS	\$ 26.75	BS2	Rear Rebound Rubber (each) Mk 5, Mk 7, Mk 8, Mk 9	\$ 25.35	Also fits the front on the Mk 4
SCJ5	Half Shaft U-Joint Fits all models with I.R.S.	\$ 37.45	R156	Rear Spring Mounting Pad, Mk 1 & 2 Attaches to the front of rear spring	\$ 10.80	
SHOCK ABSORBERS			Front Wheel Bearings			
Koni Shock Absorbers. Koni shocks are covered by a lifetime warranty to the original purchaser			CNB1	Countershaft Needle Bearings. Manual Trans (58 per pkg) Mk 7, Mk 8, Mk 9	\$ 55.65	
KS6	Front Shock, 420G, Mk 10	\$145.00	RBG1	Front Inner Wheel Bearing	\$ 21.50	
KS7	Front Shock, Mk 1, Mk 2, 3.8S, 420	\$145.00	RBG2	Front Outer Wheel Bearing, Mk 5, Mk 7, MK 8, Mk 9	\$ 17.00	
KS8	Rear Shock, 3.8S, 420, 420G, Mk 10 With I.R.S. (each) (4 required)	\$145.00	RBG22	Front Inner Wheel Bearing, Mk 1	\$ 14.25	
KS9	Rear Shock. All sedans without I.R.S. 56-69	\$145.00	RBG20	Front Outer Wheel Bearing, Mk 1	\$ 15.95	
KS14	Front Shock, Xj6, XJ12, XJS	\$ 71.50	RBG7	Front Inner Wheel Bearing	\$ 13.35	
KS15	Rear Shock, XJ6, XJ12, XJS (each) (4 req)	\$ 94.00	RBG8	Front Outer Wheel Bearing, Mk 2, Mk 10, 420, 420G, 3.4S, 3.8S. All XJ's up to 1976. Outer bearing I.D./shaft size 3/4"	\$ 9.90	
Sterling Shock Absorbers. These shocks are supplied to UNIPART and are covered by a two year warranty.			RBG6	Front Inner Wheel Bearing	\$ 13.70	
ST1	Front Shock, XJ6, XJ12, XJS	\$ 60.00	RBG5	Front Outer Wheel Bearing,. All XJ's from 1977 Outer bearing I.D./shaft size 7/8"	\$ 11.70	
ST2	Rear Shock, XJ6, XJ12, XJS (each) (4 req)	\$ 65.00	Rear Wheel Bearings			
Shock Absorber Bushings			RBG3	Rear Hub Bearing, ENV type axle Mk 5	\$ 27.70	
R124	Tubular Shock Eye Bushings. Fits all shocks above, 2 required for each end of shock that uses this type of bushings	\$ 2.95	RBG4	Rear Hub Bearing, Salisbury Axle, Mk 7, Mk 8, Mk 9	\$ 28.20	
Rebuilt Steering Racks			RBG18	Rear Hub Bearing, Mk 1, MK 2	\$ 20.00	
PSR3	Power Steering Rack, Exchange XJ6 and XJ12 with carburetors	\$450.00	RBG9	Rear Wheel Outer Bearing (each) (2 req) All models with I.R.S.	\$ 37.90	
PSR4	Power Steering Rack, Exchange All sedans with fuel injection	\$450.00	RBG10	Rear Wheel Inner Bearing (each) (2 req) All models with I.R.S.	\$ 35.30	
Rack and Pinion Parts			Differential Bearings			
R102	Rack Boot, Non-power Rack (each) (2 req)	\$ 15.40	REB1	Rear Pinion Shaft Bearing-Mounts to crown wheel and Pinion. Mk 5	\$ 32.50	
R104	Rack Boot, Power Racks (each) (2 req)	\$ 18.60	REB2	Front Pinion Shaft Bearing, Mk 5	\$ 29.90	
12019	Power Steering Rack Locktabs (each)	\$ 3.75	REB3	Differential Case Bearing (each) (2 req) Mk 5	\$ 27.70	
8316	Power Steering Box, Seal & O-Ring Kit Most boxes 420, 420G	\$ 49.00	REB7	Front Pinion Shaft Bearing. Mk 7, MK 8, Mk 9, Mk 1, Mk 2, Mk 10, 420, 420G, 3.4S, 3.8S, XJ6, XJ12, XJS	\$ 21.15	
			REB6	Rear Pinion Shaft Bearing, Mk 7, Mk 8, MK 9, Mk 1, Mk 2, Mk 10, 420, 420G, 3.4S, 3.8S, XJ6, XJ12, XJS	\$ 27.80	

REB4	Differential Case Bearing (each) (2 req) Mk 7, Mk 8, MK 9	\$ 25.60	SS20	Rear Seal, Std Trans w/o OD Mk 1, MK 2, 3.4S, 3.8S	\$ 10.00
			SS13A	Rear Seal, Overdrive Unit. Mk 8, Mk 9, Mk 1, Mk 2 3.4S, 3.8S I.D. size 1-5/8"	\$ 6.50
REB5	Differential Case Bearing (each) (2 req) MK 9 with Thornton Powerlock Differential Mk 1, 2.4 Mk 2	\$ 30.50	SS15	Front Seal, Std Trans. Mk 7, Mk 8, Mk 9, Mk 1, early MK 2 I.D. size 1-7/16"	\$10.15
REB**	Differential Output Shaft Bearing (each) (4 required)	*****	SS21	Front Seal, Std Trans. Late 3.4 Mk 2, 3.8 Mk 2, 3.4S, 3.8S I.D. size 1-1/8"	\$ 10.25
RBG30	Fulcrum Shaft Bearing, all IRS (each) (4 required)	\$ 33.50	SS25	Rear Seal, Std Trans. 420, 420G, XJ6, XJ12, XJS	\$ 8.25
Automatic Trans					
C3930	Center Bearing Carrier Support Bushing MK 7, Mk 8, Mk 9, Mk 1, Mk 2 w/automatic transmission (each) (2 req)	\$ 4.20	SS16	Front Seal, Auto Trans Mk 8, Mk 9	\$ 7.25
			SS17	Rear Seal, Auto Trans M 8, Mk 9, Mk 1, Mk 2, 3.4S, 3.8S Mk 10, 420, 420G, XJ6	\$ 10.25
Wheel Bearing and Seal Kits			Wheel Seals		
FBGK1	Front Axle Wheel Bearing Kit. Contains 2 each of RBG1, RBG2, SS8 & H75 Mk 7, MK 8, MK 9	\$ 74.15	SS8	Front Wheel Seal, Mk 5, Mk 7, MK 8, Mk 9	\$ 3.25
			SS14	Front Wheel Seal (2 req) All sedans up to 1976 Seal I.D. is 1-11/16"	\$ 13.90
RBK1	Rear ENV Axle Bearing Kit. Contains 2 Each of RBG3, SS3 & SS18. Mk 5	\$115.90	SS14A	Front Wheel Seal (2 req) All sedans from 1977 Seal I.D. is 1-7/8"	\$ 7.50
RBK2	Rear Salisbury Axle Bearing Kit. Contains 2 each of RBG4, SS6, SS7, H51, H76 And one GA7 MK 7, Mk 8, MK 9	\$132.50	Axle Seals		
			SS18	Rear Hub Outer Axle Seal Mk 5	\$ 8.75
			SS3	Rear Wheel Inner Axle Seal Mk 5	\$ 21.40
OIL SEALS			SS6	Outer Rear Wheel Seal Mk 7, MK 8, Mk 9	\$ 17.65
Differential Seals			SS7	Rear Hub Inner Axle Seal Mk 7, Mk 8, MK 9	\$ 23.55
SS4	Pinion Seal, Mk 5	\$ 21.40	SS28	Rear Hub Inner Axle Seal Mk 1, MK 2	\$ 10.00
SS5	Pinion Seal. Fits all Salisbury differentials and most I.R.S.	\$ 21.70	SS29	Rear Hub Outer Axle Seal Mk 1, Mk 2	*****
JLM527	Pinion Seal, IRS with ## I.D.	\$ 26.00	SS22	Rear Hub Inner Seal (each) (2 req) Mk 10, 3.4S, 3.8S, 420, 420G, all XJ's	\$ 9.75
SS26	Output Flange Seal (each) (2 req) fits I.R.S.	\$ 32.10	SS24	Rear Hub Outer Seal (each) (2 req) Has an inner diame- ter of @ 2 3/8". Mk 10, 3.4S, 3.8S, 420, 420G (up to 1965?)	\$ 16.00
Engine Seals			SS23	Rear Hub Outer Seal (each) (2 req) 1965 on ?. Has an inner diameter of @ 3". XJ6, XJ12, XJS	\$ 10.25
SS12	Tach Drive Seal. Mk 1, Mk 7, Mk 8 And some Mk 9	\$ 11.30	GA63	Pinion Seal Gasket, Salisbury Axle	\$ 4.75
SS30	Timing Cover Seal, 6 cyl	\$ 8.25	GA64	Outer Axle Seal Holder, Salisbury Axle (2 required)	\$ 4.75
SS32	Timing Cover Seal, 12 cyl	\$ 8.25	Miscellaneous Seals		
SS13	Rear Seal, Std Trans w/o OK Mk 7, Mk 8, Mk 9 I.D. size 1-7/16"	\$ 11.35	SS2	Oil Filter Body Seal. Fits inside cannister below filter plate. Mk 7, Mk 8, Mk 9	\$ 1.60

SS11	Steering Shaft Seal Mk 5, Mk 7	\$ 5.75	H37	Brass Exhaust Manifold Nut Set. Brass nuts and stainless lock washers (16 pcs of each) Used on manifold to cylinder head. All 6 cylinder	\$ 4.75
Power Steering Pump Seal Kit					
SS31	Power Steering Pump Seal Kit. Hebron Eaton Type. Fits Mk 2, MK 8, Mk 9	\$ 9.50	H40	Exhaust Manifold Studs (each) Cylinder head to manifold All 6 cylinder (16 required)	\$.70

TIRES & WHEELS

C46	Chrome Wire Wheel (each) Fits Mk 2, 3.4S, 3.8S	\$307.50	H50	Brass Exhaust Manifold Flange Nuts All models (set of 8 3/8" nuts and stainless washers)	\$ 3.85
			H70	Exhaust Flange Stud, all models, Threads are coarse/fine	\$.90

C46L	Knock-off for C46 wire wheel, Left Hand	\$ 53.50	C2369	Exhaust Flange Stud, all models, Threads are fine/fine	\$ 1.95
------	---	----------	-------	--	---------

C46R	Knock-off for C46 wire wheel, Right Hand	\$ 53.50	Exterior Hardware		
------	--	----------	--------------------------	--	--

WWHR	Wire Wheel Hub Resplining (each) Approx 2 week turnaround time after we receive your old hub(s).	CALL	H53	1/4" Fender Washer (plain as original) Used to hold the front fenders and various panels to the nose. Also used inside the body to secure panels	\$.70
------	--	------	-----	--	--------

TIR1	Avon Tire, 6.00-V16, 7 rib straight-shouldered design, 6 ply6 construction and V-rated for speeds in excess of 130 mph	NLA	H54	5/16" Fender Washer (plain as original) See H53 for description	\$.70
------	--	-----	-----	---	--------

TIR2	Avon Tire, 205/70/VR15. Turbospeed steel radial with "open block" tread configuration Tires have 2 plies each of rayon, steel and nylon and are "V" rated for speeds over 130 mph. Fits XJ6, XJ12 and XJS	NLA	H140	Bumper Bolt, Stainless-Bolt with stainless nut & lock washer Fits Mk 7, Mk 8, Mk 9	\$ 2.30
------	---	-----	------	--	---------

TIR3	Avon Tire, 185/HR15. Steel-belted radial with 7 rib tread pattern. "H" rated for speeds up to 130 mph. Fits Mk 1, Mk 2, 3.4S, 3.8S	NLA			
------	--	-----	--	--	--

TUB1	Tire Tube, 16"	\$ 16.00			
------	----------------	----------	--	--	--

TUB2	Tire Tube, Radial, 15" Used with wire wheels and TIR2	\$ 16.00			
------	--	----------	--	--	--

TUB3	Tire Tube, Radial, 15" Used with wire wheels and TIR13	\$ 16.00			
------	---	----------	--	--	--

TRB1	Rim Band for wire wheels, 16"	\$ 6.75			
------	-------------------------------	---------	--	--	--

TRB2	Rim Band for wire wheels, 15". These protect the tube from the spoke ends inside of the tire	\$ 6.75			
------	--	---------	--	--	--

C993	Tire Tube Valve Extractor Tool	\$ 4.25			
------	--------------------------------	---------	--	--	--

HARDWARE

Engine Compartment Hardware

H35	Chrome Plated Carburetor Bell Screw S.U. only	\$ 1.15			
-----	---	---------	--	--	--

H36	Stainless Steel Intake Manifold Nut Set Nuts & lock washers (40 pcs of each) All 6 cylinder's	\$ 11.80			
-----	---	----------	--	--	--

Interior Hardware		H17C	Slotted Head Trim Screw Kit. Fits all earlier sedans and is suitable for wood trim and vinyl trim panels. Contains:	\$ 14.50
H44	Door Panel Clips, XJ6, XJ12, XJS	\$ 1.15	(50) short stainless screws (50) long stainless screws (50) wood washers (50) trim washers	
Trim Attachment Rivets				
These rivets have special heads which fit inside of the mounting channels on the back side of the various chrome trim strips. Measure the width of the channel and match the appropriate size. The original fasteners are no longer available for the older sedans and we have found these rivets to be suitable replacements.				
H91	Trim Rivet, 5/16" head diameter	\$.45	H48 Phillips Head Trim Screw Kit. XJ6, XJ12—Contains:	\$ 8.50
H93	Trim Rivet, 1/2" head diameter	\$.75	(25) #4 x 5/8" screws (25) #4 x 1" screws (50) stainless sheetmetal screws (50) countersunk wood finish washers	
Snaps-All Types		Wiring Harness Clips		
"Lift-the-Dot", Tenax, Durable		These are the cad-plated metal clips which are used to fasten the wiring harnesses to the various body panels. Until we develop complete sets, they are sold individually, as required.		
H12	"Lift the Dot" Snap. Used on some tops	\$ 1.10	E19 Split Push Connector for Wire Ends	\$.95
H13	"Lift the Dot" Snap Plate. Used on some tops	\$ 1.00	WHC1 3/16" I.D. with a 1/4" mounting bolt hole	\$ 1.00
H25	"Lift the Dot" Stud Machine Screw. Used on the windshield posts and on the cowl to fasten the tonneau on.	\$ 5.25	WHC2 3/16" I.D. with a 5/16" mounting bolt hole	\$ 1.25
H26	"Lift the Dot" Stud Sheetmetal Screw	\$ 1.00	WHC3 5/16" I.D. with a 3/16" mounting bolt hole	\$ 1.35
H26A	"Lift the Dot" Plate (2 pieces) Used on the tonneau and on some tops	\$ 1.50	WHC4 3/8" I.D. with a 3/16" mounting bolt hole	\$ 1.00
H28	Snap Socket. Used on the back side of the snap button on rugs and tops	\$.50	WHC5 1/2" I.D. with a 3/16" mounting bolt hole	\$ 1.20
H29	Snap Stud. Used on firewalls, floorboards And bodies	\$.50	WHC6 1/2" I.D. with a 1/4" mounting bolt hole	\$ 1.25
H30	Snap Eyelet. Backing piece behind stud in a few areas such as rugs	\$.40	WHC7 3/4" I.D. with a 3/16" mounting bolt hole	\$ 1.65
H31	Snap Button (black enamel) Used on all model rugs	\$.50	WHC8 Ground Wire Connecting Clip. Usually used in head-light area for grounding connection	\$ 3.75
H32	Snap Button (nickel finish) Used on most model tops and tonneaus	\$.50	Miscellaneous Hardware	
H18	Plastic Carpet Socket (female)	\$ 1.15	H58 Panel Drill Bits (pair) Used for pilot holes on the interior panels. (all models) 5/64" bits	\$ 2.25
H19	Plastic Carpet Socket (male)	\$ 1.25	H60 1/4" Internal Lock Star Washers Stainless Steel (pkg of 25)	\$ 1.25
Interior Trim Screws			H61 5/16" Internal Lock Star Washers Stainless Steel (pkg of 25)	\$ 2.30
H55	Instrument Panel Fixing Screw (each) Has black plastic head and fits most sedans (2 required)	\$ 3.60	H62 3/8" Internal Lock Star Washers Stainless Steel (pkg of 25)	\$ 3.25
			H100A Nylon Mounting Clamp, 1/4". Used to fasten brake and fuel lines to the chassis and sheetmetal	\$.50
			H100B Nylon Mounting Clamp, 5/16"	\$.50
			H100C Nylon Mounting Clamp, 3/8"	\$.50

P A I N T					
			D8	Headlight Switch Lettering Decal Mk 7, Mk 8, Mk 9, all without foglights	\$ 2.30
ME	Seat Paint (pint) Correct Jaguar Color	\$ 18.75			
MFB	Black Engine Enamel (pint) Used on all engine blocks	\$ 11.50	D11	“Premium Oil 20/40” Air Filter Decal Round, white with black letters - XJ12, XJS	\$ 4.50
MFG	Green Engine Enamel (1/2 pint) Used on all 3.4 cylinder heads	\$ 11.50	D13	“12V Lucas Coil” Decal, Silver with black letters Mk 8, Mk 9	\$ 3.50
MFS	Silver Engine Enamel (pint) Used on Mk 7 cylinder heads (3-1/2L)	\$ 11.50	D14	“Lucas” Battery Decal, Silver with red letters Mk 1, Mk 2, 420, 420G, Mk 10	\$ 4.75
PK201	Blue Engine Enamel (11oz spray can) Used on all 3.8 cylinder heads Except Mk 10	\$ 7.75	D15	“Jaguar” V12 Cam Cover Decal, Black with white letters XJ12, XJS	\$ 3.50
PK203	Black Engine Enamel (11oz spray can) Used on all engine blocks	\$ 7.75	D18	“Tappet Clearance” Decal, Silver with red letters XJ6	\$ 5.25
PK207	Silver Engine Enamel (11oz spray can) Used on Mk 7 cylinder heads	\$ 7.75	D20	Firing Order and Tappet Clearance Decal. Mounts on driver side air cleaner....XJ12, XJS	\$ 5.75
PK223	Gold Engine Enamel (11oz spray can) Used on Mk 10 cylinder heads	\$ 7.75	D21	Lubrication Information Decal. Mounts on passenger side air filter box....XJ12, XJS	\$ 3.75
PK213	Silver Hammertone (12oz spray can) Used on wiper motors, filter boxes, etc	\$ 9.75	D25	“Trico Solvent” Decal. Mounts to washer bottle holder Mk 8, Mk 9	\$ 3.50
PK217	Black Wrinkle Paint (12oz spray can) Used on ash trays, etc.	\$ 7.75	D26	“Replace Your Wiper Blades” Decal. Mounts on washer bottle lid. Round decal, red and black with white letters Mk 8, Mk 9	\$ 2.50
PK340	Gloss Black Lacquer (12oz spray can) Used as required	\$ 7.75	D30	Emissions Control Decal, 1969 XJ6	\$ 9.00
			D31	Emissions Control Decal, 1970 XJ6	\$ 9.00
PK344	Flat Black Lacquer (12 oz spray can) Used as required	\$ 7.75	D32	Emissions Control Decal, 1971 XJ6	\$ 9.00
			D33	Emissions Control Decal, 1972 XJ6	\$ 9.00
PKT1	Glass Black Enamel (12 oz spray can) Used as required	\$ 5.20	D43	Run-in Decal for Windshield 4” diameter	\$ 3.50
			D49	Run-in Decal for Windshield 4” diameter (blue)	\$ 4.25
PKT41	Dull Aluminum Lacquer (12 oz spray can) Used as required	\$ 5.20	D44	“JAGUAR” Wing Window Decal 4” diameter	\$ 4.50
			D45	British Flag Decal for Window	\$ 4.75

EMBLEMS & DECALS

Data Plates

D2	Fusebox Layout Decal, Silver and Black Mk 8, Mk 9	\$ 4.25		The data plates are mounted on the firewalls for lubrication specifications and for vehicle identification (chassis no., engine no., and gearbox no.)	
D3	Air Filter Decal (pair) Mk 8, Mk 9	\$ 5.00	LUB1	Lubrication/Data Plate, Mk 7	\$ 42.80
D7	Headlight Switch Lettering Decal Mk 7, Mk 8, Mk 9, all with foglights	\$ 2.30	LUB2	Lubrication/Data Plate, Mk 8	\$ 20.35
			ID1	“Made in England” Tag. Usually riveted in the engine compartment. Used on all sedans up to and including XJ6	\$ 5.95

Emblems			Light Housings		
BDG8	“JAGUAR” Logo on Trunk Lid	\$ 19.20	SH1	Sidelamp Housing (each) This is a replacement side-lamp housing made of sheetmetal and must be welded on	\$ 55.40
BDG10	“4.2” Logo on Trunk Lid	\$ 14.95			
BDG20	Horn Button, Mk 7	*****	R168	“O Ring Seal” for Sidelights (each) This is for welded on only (2 required)	\$ 3.25
BDG21	Horn Button, Mk 8, Mk 9	\$106.50			
BODY FITTINGS & CHROME			Nuts and Washers		
Exterior			C36	Chromed Acorn Cylinder Head Nuts (each) (14 req)	\$ 4.75
C27	License Plate Light Housing, Mk 9	\$170.50	C37	Chromed Acorn Cam Cover Nuts (each) (22 req for cam covers) (4 required for breather vent)	\$ 3.25
C33	Headlight Rim, Mk 8, Mk 9	\$ 55.65	C38	Chromed Cyl. Head Washers “D” Shaped (each 12 req)	\$ 2.75
H14	Stainless Steel Headlight Rim Screw (2 req) Fits Mk 7, MK 8, MK 9	\$ 5.50	C38A	Chromed Cyl. Head Washers, Round (each 4 required)	\$ 3.50
A C C E S S O R I E S					
C18	Headlight Rim Upper Motif, Mk 5, Mk 7	\$ 23.75	Spoke Brushes		
C18A	Headlight Rim Upper Motif, Mk 8, Mk 9	\$ 21.40	MA	Spoke Brush	CALL
C18C	“L” Shaped Mounting Bracket. For upper headlight rim motif. Mk 5	\$ 6.25	Car Covers		
C18B	Headlight Rim Lower Motif MK 5, Mk 7, MK 8, Mk 9	\$ 21.40	Our Covercraft car covers are constructed of Technalon, a virtually waterproof yet breathable polypropylene fabric manufactured by Kimberly-Clark. They are soft against the paint yet impervious to rot and mildew		
C18D	Mounting Bracket (each) For lower headlight Rim Motif. Mk 5	\$ 14.95	COVER2	Mk 2	CALL
C18E	Backing Plate for Lower Motif Mk 5, MK 7, MK 8, Mk 9	\$ 6.25	COVER3	3.8 “S”	CALL
C80	Large Leaping Jag for Hood	\$ 45.00	COVER8	XJ6 & XJ12, Series I and II	CALL
C81	Small Leaping Jag	\$ 35.00	COVER9	XJ6 Series III	CALL
Hubcaps			COVER10	XJS	CALL
C40	Hubcap, New Chrome Reproduction (each) Mk 7, Mk 8, Mk 9 (4 required)	\$ 32.10	Jaguar Quarterlies		
C41	Hubcap Medallion for C40 This comes with the fastening clips	\$ 12.30	These quarterlies were printed and circulated by Bassett’s over a number of years past, however, there are still two issues left. Each contains several articles which we feel can still be an enormous help to the Jaguar owner. Quarterlies are only for reference. Any and all prices contained in them are invalid.		
Interior Pieces			JQ1	Jaguar Quarterly 1977 Issue Number One	\$ 3.25
C70	Steering Column Spring Mk 7, Mk 8, MK 9, Mk 1	\$ 28.95	JQ3	Jaguar Quarterly 1977 Spring Issue Salmon with Brown Ink Cover	\$ 3.25
C70A	Endcap for C70 (large)	\$ 17.90		Mk 7 service bulletins	
C70B	Endcap for C70 (small)	\$ 17.90		2.4 Mk 1 service bulletin	
C10	Chrome Still Strips (set of 4) Mk 8, Mk 9	\$120.00		Mk 8 motor specifications	
				Mk 2 service bulletin	
				XJ service bulletins	

Literature

During the past years, we have acquired a fairly extensive library of Service Manuals, Spare Parts Catalogues and other Assorted Literature. We have decided to make these available for our customer's convenience. They are being offered spiral bound and on excellent quality paper with very good reproductions of the original drawings and prints. Many of these have not been offered before and are very useful to have. The following list is available now with many more in production. If you don't see your manual, call to inquire about availability.

L8	XK120 & Mark 7 Service Manual	\$ 58.85
L9A	Service Manual Supplement, XK140 Repro	\$ 8.75
L9B	Service Manual Supplement, XK150 Repro	\$ 8.75
L9C	Supplement, Work Shop Manual, Mark 8	\$ 8.75
L9D	Supplement, Work Shop Manual, Mark 9	\$ 8.75
L34	Mark 4 Service Manual 1946-1948	\$ 42.80
L42	420 Service Manual	\$ 64.20
L52	Daimler SP.250 Service Parts Manual	\$ 37.45
L53	Mark 10 3.8 Service Manual	\$ 69.55
L81	Shop Manual, 3.4S and 3.8S	\$ 69.55
L19	XKE Ser 3, V.12 Shop Manual	\$ 76.00
L44A	XKE 3.8 Service Manual	\$ 64.20
L44B	XKE 4.2 Supplementary Service Manual	\$ 31.05
Spare Parts Catalogues		
L10	SS100 & Mark 4 Spare Parts Catalogue	\$ 46.00
L11	Mark 5 Spare Parts Catalogue	\$ 48.15
L12	Mark 7 Spare Parts Catalogue	\$ 42.80
L26	Mark 8 Spare Parts Catalogue	\$ 53.50
L27	Mark 9 Spare Parts Catalogue	\$ 53.50
L28	Mark 1 Spare Parts Catalogue, 2.4	\$ 53.50
L28A	Mark 1 Spare Parts Catalogue, 3.4	\$ 53.50
L81A	Spare Parts Catalogue, 3.4S and 3.8S	\$ 53.50
L20	XK 120 Spare Parts Catalogue	\$ 32.10
L21	XK 120 D.H.C. Spare Parts Catalogue	\$ 20.00
L22	XK 120 Coupe Spare Parts Catalogue	\$ 21.40
L23	XK 140 Spare Parts Catalogue	\$ 48.15
L24A	XK 150 Spare Parts Catalogue, Part 1	\$ 58.85
L24B	XK 150 Spare Parts Catalogue, Part 2	\$ 42.80
L44	XKE 3.8 Spare Parts Catalogue	\$ 42.80
L45	XKE 4.2 Spare Parts Catalogue	\$ 42.80
L46	XKE Ser 3 Roadster Spare Parts Catalogue	\$ 40.65
L47	XKE Ser 3 Coupe Spare Parts Catalogue	\$ 40.65

Assorted Literature

L25	Delanair Air Conditioning Service Manual	\$ 32.10
L25A	York Air Conditioning Service Manual	\$ 32.10
L31	Automatic Transmission Service Manual-XK 140, Mk 7	\$ 26.75
L40	Auto Transmission Spare Parts Catalogue, XK 140, Mk 7	\$ 26.75
L33	Mark 7 Laycock Overdrive Service Manual	\$ 16.00
L33A	Laycock De Normanville OD Parts Catalogue	\$ 26.75
L36	Power Steering Service Manual, Mk 2, Mk 8, Mk 9	\$ 16.00
L37	Dunlop Disc Brake "D" Competition Car	\$ 13.35
L38	SU Carburetor & Fuel Pump Service Manual	\$ 40.65
L43	Vac-Hydro Brake Servo Service Manual, Mk 7	\$ 13.35

Service Manuals

L80	Mk 2 - Covers 2.4, 3.4, 3.8	\$ 70.00
L81	3.4S, 3.8S	\$ 69.55
L82	XJ6 Series I	\$ 50.00
L83	XJ6 Series II (394 pages)	\$ 65.00
L84	XJ12 Series II (362 pages)	\$ 65.00
L85	XJ6 and XJ12, Series III 15 individual sections in a looseleaf binder	\$110.00
L86	XJS 1976-77 (270 pages)	\$ 25.00
L87	XJS 1978 on (386 pages) Has XJS HE supplement	\$ 74.95
L15	XJ6 Exhaust Emissions and Fuel Evaporation Controls Manual (16 pages) Series I	\$ 5.25
L41	Stromberg Carburetor Tuning Book (33 pages) Contains tuning information, specifications and measurements	\$ 7.50

Maintenance Charts

These are the charts which were originally supplied with the owner's handbooks. They measure 28" by 21"

L32	3.4S, 3.8S	\$ 3.00
L39	Mk 9	\$ 3.00

Owner's Handbooks

Handbooks are the factory-supplied operating, maintenance and service books which came in the glovebox. Supplies of the originals are very limited.

L2	Mk 4 Handbook (67 pages)	\$ 12.50
L3	Mk 5 Handbook (49 pages)	\$ 12.50
L4	Mk 9 Handbook (70 pages)	
	Includes maintenance chart	

Posters

The following posters are all reproductions of the centerfold drawings that were featured in the "JAGUAR QUARTERLY" magazine. All the posters were drawn by Dennis Simon for the quarterly.

P1	XK 120 Roadster Poster Black ink on Driftwood Tan 12" x 25"	\$ 4.25
P2	History of XK 120 Poster Black ink on Ivory 12" x 25"	\$ 4.25
P3	XK-SS Poster Black ink on Valley Forge Brick 15" x 25"	\$ 4.25
P4	XKE Series 1 Coupe Black ink on Yellow 15" x 25"	\$ 4.25
P6	Mark 9 Saloon Blue ink on Light Blue 15" x 25"	\$ 4.25
P7	XKE Series 1 Roadster Blue ink on Grey 15" x 25"	\$ 4.25
P9	History of XK 120 Large Poster Black ink on Ivory 17" x 36"	\$ 7.25